


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*njm/w/31015645*

Name of Company		COG OPERATING LLC <i>229137</i>	Contact	Pat Ellis	<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Address		600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077		
Facility Name		YUCCA STATE <i>(Willow State)</i>	Facility Type	TANK BATTERY		
Surface Owner			STATE	Mineral Owner		
			Lease No. (API#) 30-015-28880			

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	16	17S	31E					EDDY

Latitude 32.82822      Longitude 103.87359

**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	9bbls	Volume Recovered	8bbls
Source of Release	1/2" valve on header	Date and Hour of Occurrence	03-23-2013	Date and Hour of Discovery	03-23-2013 11:00pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
1/2" valve on header was partially open. Closed valve to prevent further release of fluids.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 9bbls were released from a 1/2" partially opened valve on the header we were able to recover 8bbls with a vacuum truck. The entire release was contained inside the lined facility. All free fluid has been recovered. Contaminated gravel has been removed from the facility. Fresh gravel has been added as necessary. The facility has been returned to its prior condition.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature:					
Printed Name:	Josh Russo	Approved by District Supervisor:			
Title:	Senior Environmental Coordinator	Approval Date:		Expiration Date:	
E-mail Address:	jrusso@concho.com	Conditions of Approval:			Attached <input type="checkbox"/>
Date:	04-03-2013	Phone:	432-212-2399		

OIL CONSERVATION DIVISION

Accepted for record  
NMOCD

\* Attach Additional Sheets If Necessary

*2RP-1615*

Accepted for record  
NMOCD

**Bratcher, Mike, EMNRD**

---

**From:** Robert Grubbs <RGrubbs@concho.com>  
**Sent:** Wednesday, April 03, 2013 1:11 PM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Tarez, Ike; tom.k.franklin@tetrattech.com; Joshua Russo  
**Subject:** C-141 Initial/Final Report - Yucca State Tank Battery  
**Attachments:** YUCCA STATE -- DATE OF RELEASE -- 03-23-2013.pdf

Mr. Bratcher,

Please see attached the C-141 Initial/Final Report for a release that occurred on 03/23/2013 at our Yucca State Tank Battery. This is a lined facility.

Thank you,

*Robert Grubbs Jr.*  
*Sr. Environmental Coordinator*  
432.683.7443 (main)  
432.818.2369 (direct)  
432.661.6601 (cell)  
[rgrubbs@concho.com](mailto:rgrubbs@concho.com)

Mailing Address:  
One Concho Center  
600 W. Illinois Avenue  
Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.