

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

MAR 20 2013

Form C-141
Revised October 10, 2003

NMOC D ARTESIA
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	OWL 20504 JV-P WELL #005	Facility Type	SWD

Surface Owner	FEDERAL	Mineral Owner		Lease No. (API#)	30-015-35135
---------------	---------	---------------	--	------------------	--------------

LOCATION OF RELEASE

35435

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	18	26S	27E					EDDY

Latitude 32.04148

Longitude 104.22825

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	10bbls	Volume Recovered	0bbls
Source of Release	Fiberglass line	Date and Hour of Occurrence	03-10-2013	Date and Hour of Discovery	03-10-2013 4:45pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*



The buried fiberglass line fractured due to traffic. The line has been replaced and added more surface material for additional padding and protection.

Describe Area Affected and Cleanup Action Taken.*

Initially an estimated 10bbls were released due to a fracture in a buried fiberglass line on location. We were unable to recover any fluids. The entire spill was contained on the location. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a work plan to the NMOC D/BLM for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D/BLM acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:		Approved by District Supervisor:	
Printed Name:	Josh Russo	Signed By 	
Title:	Senior Environmental Coordinator	Approval Date:	APR 05 2013
E-mail Address:	jrusso@concho.com	Expiration Date:	
Date:	03-20-2013	Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	432-212-2399		

* Attach Additional Sheets If Necessary

Remediation per OCD Rule &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NO LATER THAN:

May 5, 2013

2RP-1599

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Wednesday, March 20, 2013 3:40 PM
To: Bratcher, Mike, EMNRD; Amos, James <jamos@blm.gov> (jamos@blm.gov)
Cc: Tavarez, Ike; tom.k.franklin@tetrattech.com; Joshua Russo
Subject: RE: C-141 Initial Report - Owl 20504 JV-P Well #005
Attachments: OWL 20504 JV-P WELL #005 SWD -- DATE OF RELEASE -- 03-10-2013.pdf

Gentlemen,

Please see the attachment for the previous E-Mail.

Thanks,

From: Robert Grubbs
Sent: Wednesday, March 20, 2013 4:34 PM
To: Mike Bratcher (mike.bratcher@state.nm.us) (mike.bratcher@state.nm.us); Amos, James <jamos@blm.gov> (jamos@blm.gov)
Cc: 'Tavarez, Ike'; tom.k.franklin@tetrattech.com; Joshua Russo
Subject: C-141 Initial Report - Owl 20504 JV-P Well #005

Gentlemen,

Please see attached the C-141 Initial Report for a release that occurred on 03/10/2013 at our Owl 20504 JV-P Well #005 in Eddy County New Mexico. We plan to assess the spill area timely.

Thank you,

Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com
Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Wednesday, March 20, 2013 3:34 PM
To: Bratcher, Mike, EMNRD; Amos, James <jamos@blm.gov> (jamos@blm.gov)
Cc: Tavaréz, Ike; tom.k.franklin@tetrattech.com; Joshua Russo
Subject: C-141 Initial Report - Owl 20504 JV-P Well #005

Gentlemen,

Please see attached the C-141 Initial Report for a release that occurred on 03/10/2013 at our Owl 20504 JV-P Well #005 in Eddy County New Mexico. We plan to assess the spill area timely.

Thank you,

Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com

Mailing Address:

One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Amos, James <jamos@blm.gov>
Sent: Thursday, March 21, 2013 6:57 AM
To: Robert Grubbs
Cc: Bratcher, Mike, EMNRD; Tavarez, Ike; tom.k.franklin@tetrattech.com; Joshua Russo
Subject: Re: C-141 Initial Report - Owl 20504 JV-P Well #005

Robert, thanks for the notification.

On Wed, Mar 20, 2013 at 3:39 PM, Robert Grubbs <RGrubbs@concho.com> wrote:

Gentlemen,

Please see the attachment for the previous E-Mail.

Thanks,

From: Robert Grubbs
Sent: Wednesday, March 20, 2013 4:34 PM
To: Mike Bratcher (mike.bratcher@state.nm.us) (mike.bratcher@state.nm.us); Amos, James <jamos@blm.gov> (jamos@blm.gov)
Cc: 'Tavarez, Ike'; tom.k.franklin@tetrattech.com; Joshua Russo
Subject: C-141 Initial Report - Owl 20504 JV-P Well #005

Gentlemen,

Please see attached the C-141 Initial Report for a release that occurred on 03/10/2013 at our Owl 20504 JV-P Well #005 in Eddy County New Mexico. We plan to assess the spill area timely.

Thank you,

Robert Grubbs Jr.

Sr. Environmental Coordinator

432.683.7443 (main)

432.818.2369 (direct)

432.661.6601 (cell)

rgrubbs@concho.com

Mailing Address:

One Concho Center

600 W. Illinois Avenue

Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.