<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II.
1301 W. Grand Avenue, Artesis, NM 88210 District III 1000 Rio Brazos Road, Azrec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505

Revised October 10, 2003 Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back

Form C-141

side of form Release Notification and Corrective Action **OPERATOR** Initial Report Final Report Name of Company OGRID Number Contact: Yates Petroleum Corporation 25575 Robert Asher Address Telephone No. 105 S. 4TH Street 575-748-1471 Facility Name API Number Facility Type Cigarillo SWD #1 30-015-21643 SWD Battery Surface Owner Mineral Owner Lease No. State State VO-7290 LOCATION OF RELEASE Range Unit Letter Section Township Feet from the North/South Line Feet from the East/West Line County 36 23\$ 27E 1980 North 1980 Eddy Past Latitude 32.26322 Longitude 104.14136 NATURE OF RELEASE Type of Release Volume of Release Volume Recovered Produced Water 390 B/PW 390 B/PW Source of Release Date and Hour of Occurrence Date and Hour of Discovery Transfer Pump 3/18/2013; AM 3/18/2013; AM Was Immediate Notice Given? If YES, To Whom? Yes □ No □ Not Required Mike Bratcher/NMOCD District II By Whom? Date and Hour Robert Asher/ Yates Petroleum Corporation 3/20/2013; AM Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☐ Yes 🗵 No If a Watercourse was Impacted, Describe Fully. Describe Cause of Problem and Remedial Action Taken.* Gasket on transfer pump developed leak. Vacuum truck called. Describe Area Affected and Cleanup Action Taken. An approximate area of 30' X 100' (inside bermed and lined battery). All released produced water was recovered. Depth to Ground Water: 50-99' (75', ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 10. Based on all produced water being recovered and battery is lined, Yates Petroleum Corporation requests closure. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Signed By Approved by District Supervisor: Printed Name: Robert Asher 2013 Title: NM Environmental Regulatory Supervisor Expiration Date: A E-mail Address: boba@yatespetroleum.com Conditions of Approval: N Attached Date: Friday, April 05, 2013 Phone: 575-748-4021 * Attach Additional Sheets If Necessary

NM Environmental Regulatory Supervisor



FACSIMILE TRANSMITTAL SHEET	
FROM:	το:
Robert Asher	Mike Bratcher/NMOCD II
DATE:	FAX NUMBER:
Friday, April 05, 2013	9-748-9720
TOTAL NO. OF PAGES INCLUDING COVER:	RE:
2	Cigarillo SWD #1
NOTES:	COMMENTS:
☐ URGENT ☑ FOR REVIEW ☐ PLEASE COMMENT ☐ PLEASE REPLY ☐ PLEASE RECYCLE	
NOTES/COMMENTS:	
INITIAL & FINAL REPORT.	
Report for 3/18/2013 release.	
If you have any questions, contact me at 575-748-4217.	
Thank you.	
Robert Asher	

Bratcher, Mike, EMNRD

From:

Bob Asher <BobA@yatespetroleum.com>

Sent:

Wednesday, March 20, 2013 10:34 AM

To:

Bratcher, Mike, EMNRD; Dade, Randy, EMNRD

Subject:

Release (Cigarillo SWD #1)

Yates Petroleum Corporation is reporting a release at the following location (3/18/2013).

Cigarillo SWD #1 30-015-21643 Section 36, T23S-R27E Eddy County, New Mexico

Released: Approximately 390 B/PW; Recovered: Approximately 390 B/O B/PW, battery is lined.

Release (information on cause not obtained yet) within the bermed/lined battery. Vacuum truck(s) were called and recovered all produced water.

A Form C-141 Initial/Final Report will be submitted with complete information.

Thank you.

Thank you.

Robert Asher

NM Environmental Regulatory Supervisor Yates Petroleum Corporation Artesia, NM 88210 575-748-4217 (Office) 575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.