

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JUN 06 2013

Form C-141
Revised October 10, 2003

NMOCD ARTESIA

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 1315847592

Name of Company		COG OPERATING LLC 229/37	OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address		600 West Illinois Avenue, Midland, TX 79701	Contact		Pat Ellis	
Facility Name		MONCRIEF STATE #001	Telephone No.		432-230-0077	
			Facility Type		TANK BATTERY	
Surface Owner			Mineral Owner			Lease No. (API#) 30-015-25017

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	23	17S	28E					EDDY

Latitude 32.81742

Longitude 104.15406

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	10bbls	Volume Recovered	7bbls
Source of Release	Murphy switch on water tank	Date and Hour of Occurrence	06-01-2013	Date and Hour of Discovery	06-01-2013 9:00am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
The murphy switch malfunctioned and did not turn on the transfer pump. We have replaced the murphy switch to prevent reoccurrence.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 10bbls of produced water were released due to a murphy switch failure on the water tank. We were able to recover 7bbls of produced water with a vacuum truck. The spill was completely contained inside the facility walls. All free fluid has been recovered. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a work plan to the NMOCD for approval prior to any significant remediation work.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature:		OIL CONSERVATION DIVISION			
Printed Name: Robert Grubbs Jr.		Approved by District Supervisor: Signed By Mike Brennan			
Title: Senior Environmental Coordinator		Approval Date: JUN 07 2013		Expiration Date:	
E-mail Address: rgrubbs@concho.com		Conditions of Approval:		Attached <input type="checkbox"/>	
Date: 06-05-2013		Phone: 432-661-6601			

* Attach Additional Sheets If Necessary

Remediation per OCD Rule &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NO LATER THAN:

July 7, 2013

2RP-1679

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Thursday, June 06, 2013 8:31 AM
To: Bratcher, Mike, EMNRD
Cc: Joshua Russo; Tavarez, Ike; tom.k.franklin@tetrattech.com
Subject: C-141 Initial Report - Moncrief State #001
Attachments: MONCRIEF STATE #001 (TANK BATTERY) -- DATE OF RELEASE -- 06-01-2013.pdf

Mr. Bratcher,

Please see attached the C-141 Initial Report for a release that occurred on 06-01-2013 at our Moncrief State #001 in Eddy County New Mexico. We plan to assess the spill area timely.

Thank you,

*Robert Grubbs Jr.
Sr. Environmental Coordinator*

432.683.7443 (main)

432.818.2369 (direct)

432.661.6601 (cell)

rgrubbs@concho.com

Mailing Address:

One Concho Center

600 W. Illinois Avenue

Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.