


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

Name of Company		Contact	
COG OPERATING LLC 229137		Pat Ellis	
Address		Telephone No.	
600 West Illinois Avenue, Midland, TX 79701		432-230-0077	
Facility Name		Facility Type	
SRO SWD #101		SWD	
Surface Owner		Mineral Owner	
STATE		Lease No. (API#) 30-015-26105	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	05	26S	28E					EDDY

Latitude 32.07351 Longitude 104.1067

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	100bbls	Volume Recovered	0bbls
Source of Release	Victaulic coupling	Date and Hour of Occurrence	06-09-2013	Date and Hour of Discovery	06-09-2013 4:00pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOCD		
By Whom?	Michelle Mullins	Date and Hour	06-12-2013 10:18am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A Victaulic coupling failed causing the release of 100bbls of produced water. The Victaulic coupling has been replaced and the line is back in service.					
Describe Area Affected and Cleanup Action Taken.*					
Initially an estimated 100bbls of produced water was released due to a Victaulic clamp that failed. We were unable to recover any fluid. The spill area is located in the pasture. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a work plan to the NMOCD for approval prior to any significant remediation work.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature:		OIL CONSERVATION DIVISION			
Printed Name:		Approved by District Supervisor:			
Robert Grubbs Jr.		Signed By <i>Mike Bratcher</i>			
Title:		Approval Date:		Expiration Date:	
Senior Environmental Coordinator		JUL 02 2013			
E-mail Address:		Conditions of Approval:		Attached <input type="checkbox"/>	
rgrubbs@concho.com					
Date:		Phone:			
06-21-2013		432-661-6601			

* Attach Additional Sheets If Necessary

Remediation per OCD Rule &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NO LATER THAN:

August 2, 2013

2RP-1693

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Friday, June 21, 2013 8:28 AM
To: Bratcher, Mike, EMNRD
Cc: Joshua Russo; Tavarez, Ike; tom.k.franklin@tetrattech.com
Subject: C-141 Initial Report -SRO SWD #101
Attachments: SRO SWD #101 -- DATE OF RELEASE -- 06-09-2013.pdf



Mr. Bratcher,

Please see attached the C-141 Initial Report for a release that occurred on 06-09-2013 at our SRO SWD #101 in Eddy County New Mexico. We plan to assess the spill area timely.

Thank you,

Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com

Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Michelle Mullins <MMullins@concho.com>
Sent: Wednesday, June 12, 2013 9:18 AM
To: Bratcher, Mike, EMNRD
Cc: Joshua Russo; Robert Grubbs
Subject: SRO 101 SWD-Immediate Notification

Mr. Bratcher:

At approximately 4:00 p.m. on 6/09/2013, a produced fluid release was discovered near the above-referenced facility. The fluid was not contained inside the battery. An estimated 100 barrels of produced fluid was released. The cause of the release is currently under investigation. We will follow up within 15 days with a C-141 Report. GPS coordinates, legal description and driving directions are below.

32.07843 104.10940

SRO 101 SWD (closest well)

Unit G, Sec 5. T26S R28E

Eddy County, NM

API 30-015-26105

From Highway 285, travel south to mile marker 5 (White's City Road). Turn west and travel 1.5 miles. Turn north and travel .6 miles. Release is on the west side of lease road.

Michelle Mullins

HSE Field Tech

2407 Pecos Avenue

P.O. Box 1630

Artesia, NM 88211-1630

Phone: (575)746-2010

Cell: (432) 934-1052

mmullins@conchoresources.com

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.