


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

### Release Notification and Corrective Action

Name of Company: BOPCO, L.P. <b>260737</b>		Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329
Facility Name: PLU-57 Tank Battery		Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-24269

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	28	25S	31E					Eddy

Latitude **N 32.094735** Longitude **W 103.785760**

### NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release: 3 bbls of crude oil and 15 bbls produced water	Volume Recovered: 2 bbls water
Source of Release: Heater Treater	Date and Hour of Occurrence: 6/7/13 time unknown	Date and Hour of Discovery: 6/7/13 1:00 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
The gasket failed on the heater treater fire tube. The gasket was replaced.

Describe Area Affected and Cleanup Action Taken.\*  
Approximately 600 sq.ft. of tank battery pad was affected by the release. The free standing fluid was recovered. The spill area will be remediated in accordance to the NMOCD and BLM guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: <i>M. L. Brandon</i>	
Title: Waste Management and Remediation Specialist		Approval Date: <b>JUL 17 2013</b>	Expiration Date:
E-mail Address: tasavoie@basspet.com		Conditions of Approval:	
Date: 7/14/13 Phone: 432-556-8730		Remediation per OCD Rule & Guidelines, & like approval by BLM. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN:</b>	
		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

**August 17, 2013**

**2RP-1730**