District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztes, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 RECEIVED

FEB **0.6** 2012. Revised October 10, 2003

NMOCD ARTES A Rule 116 on back side of form

| Nelease Nothication and Corrective Actions OPERATOR ☐ Initial Report ☐ Final Rep | |
|---|--|
| Name of Company Southern Union Gas Services 3495) | Contact Rose Slade |
| Address 801 S. Loop 464 Monahans, Texas 79756 | Telephone No. 432-940-5147 |
| Facility Name California A (2011-09-011) | Facility Type Natural Gas Pipeline |
| Surface Owner Burcau of Land Management Mineral Owner | r API No 30-025-28822 |
| | ON OF RELEASE |
| Unit Letter: Section Township Range Feet from the Nort | th/South Line Feet from the East/West Line County Eddy |
| Latitude 32 degrees 03 85 | 53'. Longitude 103 dégrées 59.814' |
| NATUR | E OF RELEASE |
| Type of Release Natural Gas | Volume of Release 195 mcf Volume Recovered None |
| Source of Release * 16-Inch Steel Pipeline (Low Pressure) | Date and Hour of Occurrence Date and Hour of Discovery Unknown September 28, 2011 |
| Was Immediate Notice Given? ☐ Yes ☐ No ☒ Not Require | If YES, To Whom? |
| By Whom? | Date and Hour |
| Was a Watercourse Reached? ☐ Yes ☑ No | If YES Volume Impacting the Watercourse. |
| If a Watercourse was Impacted, Describe Fully * | A STATE OF THE STA |
| | |
| | |
| Describe Cause of Problem and Remedial Action Taken.* | |
| Failure of a segment of the sixteen (16) inch low pressure steel pipeline pipeline clamp to mitigate the release. | resulted in the release of natural gas. The pipeline was fitted with a temporary |
| e e e e e e e e e e e e e e e e e e e | |
| Describe Area Affected and Cleanup Action Taken.* Pipeline was clamped and placed back in service | |
| | |
| | the best of my knowledge and understand that pursuant to NMOCD rules and |

public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other.

Approval Date

Conditions of Approval:

Approved by Environmental Specialist:

Expiration Date:

29 2013

E-mail-Address rose slade@sug.com

Date: December 19, 2011 Phone: 432-940-5147

Attach Additional Sheets If Necessary:

FJMW 1321033522

IJMW 132103 4342

federal, state, or local laws and/or regulations

Signature:

Printed Name: Rose Slade

Title: EHS Compliance Specialist

2RP-17100

Attached 🔝

Bratcher, Mike, EMNRD

From:

Inskeep, Cyndi M. [Cyndi.Inskeep@SUG.com]

Sent: To: Monday, February 06, 2012 10:49 AM Bratcher, Mike, EMNRD

Cc:

Slade, Rose

Subject:

C141

Attachments:

Various Sept 2011.pdf

Mr. Bratcher:

You will find attached a C-141 for the following:

California B (4) California A

Thank you,

Cyndi Inskeep

EHS Associate
Southern Union Gas Services
801 S. Loop 464
Monahans TX 79756
email: cyndi.inskeep@suq.com
817-302-9720 phone
432-638-5328 cell
817-302-9701 fax

Southern Union Gas Services

Private and confidential as detailed here. If you cannot access hyperlink, please e-mail sender.

All Coss Puel Ext