<u>District 1</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u>						f New Mexico and Natural Resources			Form C-141 Revised August 8, 2011				
1301 W. Grand Avenue, Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505				1220 South			rvation Division h St. Francis Dr. e, NM 87505			Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.			
		•	Rele	ease Notifi	catio	on and Co	orrective A	ctio	n	с			
MMU	321137	11	0			OPERA			🔲 Initi	al Report	🛛 Final Report		
Name of Company Enterprise Field Services LLC 10003477 PO Box 4324, Houston, TX 77252						Contact Jim Heap Telephone No. 432-686-5404							
Facility Name Pipeline ROW, Trunk A Line						Facility Type: Gas Gathering Pipeline							
Surface Owner	Mineral	Owner	NA Lease No. NA										
			LOC	ATIC	DN OF RELEASE								
Unit Letter Secti		ip	Range 31E	Feet from the		h/South Line	Feet from the	East/	West Line	County Eddy			
· · · · · · · · · · · · · · · · · · ·	233			titude: <u>32.320</u>	741 N	Longitu	ide: <u>-103.8104</u>	10 W			· · ·		
			La					10 W					
Type of Release N	atural Gas			INA.	IURI	E OF REL Volume of	EASE f Release 175 N	1CF	Volume I	Recovered	0		
Source of Release Pipeline Leak						Date and Hour of Occurrence Date and Hour of Discovery							
Was Immediate Notice Given?						If YES, To Whom?							
Yes No Not Require						Date and I	lour						
By Whom? Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.							
			14		==N/								
If a Watercourse was Impacted, Describe Fully.*						FEB 2 8 2013							
Describe Cause of I) ach long on d D		lial Aatia	n Talian *				NARIA	CD AR	TESIA			
					hen the	line was return					ort of leak on 02-10-		
2013) Describe Area Affe	cted and Clean	up A	ction Tal	(en.*					z		•		
I hereby certify that regulations all oper- public health or the should their operati- or the environment. federal, state, or loc	ators are requir environment. ons have failed In addition, N	red to The l to a IMO	report an acceptanc dequately CD accep	nd/or file certain ce of a C-141 rep investigate and	release ort by t remedia	notifications a the NMOCD n ate contaminat	nd perform corre narked as "Final F ion that pose a th	ctive ac Report" reat to g	tions for rel does not rel ground wate	eases which ieve the ope r, surface w	n may endanger erator of liability ater, human health		
Signature:						OIL CONSERVATION DIVISION							
Printed Name: Matthew E. Marra						Approved by	District Supervis	sor:	Acce	pted for			
						JI.	JL 3 0 2013	}		NMOCI	0		
Title: Senior Director - Environmental						Approval Da	te:	`	Expiration	Date:			
E-mail Address: memarra@eprod.com Date:2-22-20/3 Phone: 713-381-6684						Conditions of Approval:				Attached	1		
Date 2022 2013 Phone: 713-381-6684 Attach Additional Sheets If Necessary FJMW 1321136854 iJMW 1321137609						L			2	ZRP	-1776		
iJMW 13	2113-	74	209										
					Ň								



ENTERPRISE PRODUCTS PARTNERS L.P. ENTERPRISE PRODUCTS HOLDINGS LLC (General Partner)

February 22, 2013

RECEIVED FEB 2 8 2013 NMOCD ARTES'S

7012 2210 0001 2197 4016 Return Receipt Requested

Mr. Mike Bratcher New Mexico Oil Conservation Division District 2 Office 811 South First Street Artesia, New Mexico 88210

RE: Form C-141 Report for Enterprise Products Gas Loss Reported in the Carlsbad Gathering Field

Mr. Bratcher:

Pursuant to 29 (19.15.29) NMAC please find enclosed the requisite C-141 Form for the release from our Trunk A line in our Carlsbad Gathering Field, Eddy County. The new release was found when returning the previously repaired line to service.

If you have any questions or need more information, please contact Jim Heap by phone at 432-686-5404, by email at <u>jkheap@eprod.com</u> or me at 713-318-6684

Regards,

Matthew E. Marra Senior Director, Environmental

/sjn attachments

P. O. BOX 4324 HOUSTON, TX 77210-4324 713.381.6500 1100 LOUISIANA STREET HOUSTON, TX 77002-5227 www.epplp.com