District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

14

23S

28E

State of New Mexicor ECEIVED State of New Prior Land Resources Energy Minerals and Natural Resources JAN 1 0 2013 Submit 1

Oil Conservation Division

1220 South St. Francis DOCD ARTESIA

Santa Fe, NM 87505

Form C-141 Revised August 8, 2011

Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Eddy

Release Notification and Corrective Action OPERATOR Initial Report Final Report Contact Jim Heap Enterprise Field Services LLC/00034/7 Telephone No. 432-686-5404 PO Box 4324, Houston, TX 77252 Facility Type: Gas Gathering Pipeline Pipeline ROW, Donaldson Lateral Line Facility Name Mineral Owner NA Lease No. NA Multiple Owners Surface Owner LOCATION OF RELEASE North/South Line Unit Letter Feet from the Feet from the East/West Line County Section **Township** Range

Latitude: N 32.300202 Longitude: W-104.058157		
NATURE OF RELEASE		
Type of Release Natural Gas	Volume of Release 200 MCF	Volume Recovered 0
Source of Release Pipeline Leak, small hole in pipe-wall.	Date and Hour of Occurrence (SI/BD) 01-03-2013 18:08 hrs	Date and Hour of Discovery 01-03-2013 15:00 hrs
Was Immediate Notice Given? ☐ Yes ☐ No ☒ Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
	,	
Describe Cause of Problem and Remedial Action Taken.*		
Small hole in the pipe-wall; suspected corrosion fault. Loss volume includes blow-down loss for repair.		
Describe Area Affected and Cleanup Action Taken.*		
The line was isolated and prepped for repairs.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
OIL CONSERVATION DIVISION		VATION DIVISION
Signature:	•	Accepted for record
Printed Name: Matthew E. Marra	Approved by District Supervisor:	NMOCD
Title: Senior Director, Environmental	Approval Date:	Expiration Date:
	Conditions of Approval:	Attached
Date: / - 4 - Zo/V Phone: 713-381-6684		000

2KY-1809


FJMW 1322138456



ENTERPRISE PRODUCTS PARTNERS L.P. ENTERPRISE PRODUCTS HOLDINGS LLC (General Partner)

ENTERPRISE PRODUCTS OPERATING LLC

January 7, 2013



7012 2210 0001 2251 2149 Return Receipt Requested

Mr. Mike Bratcher New Mexico Oil Conservation Division District 2 Office 811 South First Street Artesia, New Mexico 88210

RE:

Form C-141 Report for Enterprise Field Services

Donaldson Lateral Release

Dear Sir:

Pursuant to 18(19,15.29) NMAC please find enclosed the requisite C-141 Form for the release on our Donaldson Lateral gathering line in Eddy County. This was an unintended release due to a small hole in the pipe-wall.

If you have any questions or need more information, please contact Jim Heap, Field Environmental Representative, by phone at 432-686-5404, by email at jkheap@eprod.com or me at 713-318-6684.

Regards,

Mätthew E. Marra

Senior Director, Environmental

/sjn