

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report


Name of Company	Enterprise Field Services LLC 1000347	Contact	Jim Heap	
	PO Box 4324, Houston, TX 77252	Telephone No.	432-686-5404	
Facility Name	Pipeline ROW, Crooked Creek Tie-in)	Facility Type:	Gas-gathering Pipeline	
Surface Owner	Mineral Owner	NA	Lease No.	NA

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	9	24S	24W					Eddy

Latitude: N 32.22705 Longitude: W -104.50468

NATURE OF RELEASE

Type of Release	Natural Gas	Volume of Release	150 MCF	Volume Recovered	0
Source of Release	Pipeline Blow-down to relieve hydrate blockage.	Date and Hour of Occurrence (Start)	01-23-2013 12:15 hrs	Date and Hour of Discovery	01-23-2013 12:30 hrs
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.* The affected section of the 6-inch line was isolated and blown-down to relieve a hydrate blockage.					
Describe Area Affected and Cleanup Action Taken.*					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Matthew E. Marra		Accepted for record NMOCD			
Title: Senior Director, Environmental & Technical Service		Approval Date: AUG 09 2013		Expiration Date:	
E-mail Address: memarra@eprod.com		Conditions of Approval:		Attached <input type="checkbox"/>	
Date: 1-24-13 Phone: 432-686-5404					

* Attach Additional Sheets If Necessary

FJMW 1322139885

JMW 1322154311


2RP-1810



ENTERPRISE PRODUCTS PARTNERS L.P.
ENTERPRISE PRODUCTS HOLDINGS LLC
(General Partner)

ENTERPRISE PRODUCTS OPERATING LLC

January 24, 2013



7012 2210 0001 2197 4474
Return Receipt Requested

Mr. Mike Bratcher
New Mexico Oil Conservation Division
District 2 Office
811 South First Street
Artesia, New Mexico 88210

**RE: Form C-141 Report
Gas Loss Reported in the Carlsbad Gathering Field**

Mr. Bratcher:

Pursuant to 29 (19.15.29) NMAC please find enclosed the requisite C-141 Form for the following two releases in our Carlsbad Gathering Field:

Line	Date	Cause & Volume
B-3 Gathering Line	01-23-2013	Purge for BOPCO Tie-ins. 300 MCF
Crooked Creek Tie-in	01-23-2013	Blow-down to clear hydrates. 150 MCF

If you have any questions or need more information, please contact Jim Heap by phone at 432-686-5404, by email at jkheap@eprod.com or me at 713-318-6684

Yours truly,

Matthew E. Marra
Senior Director, Environmental

/sjn
attachments