District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised August 8, 2011 Submit 1 Copy to appropriate District Office in

Form C-141

accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action OPERATOR** Initial Report Final Report Name of Company: Enterprise Field Services LLC 1000347 Contact: Jim Heap Address: PO Box 4324, Houston, TX 77252 Telephone No.: 432-686-5404 Facility Name: Pipeline #1002 Facility Type: Gathering Pipeline Mineral Owner API No. Surface Owner LOCATION OF RELEASE Feet from the North/South Line Feet from the East/West Line Unit Letter Section **Township** Range County 25S 28E Eddy 2 Latitude: N 32.123029 Longitude: W -104.328811 NATURE OF RELEASE Type of Release: Natural Gas Volume of Release: 9,444 Mscf Volume Recovered: 0 Source of Release: Date and Hour of Discovery: Date and Hour of Occurrence: Start: 06/27/2013 16:30 (MDT) Pressure Relief Valve release. End: 06/28/2013 01:30 (MDT) Was Immediate Notice Given? If YES, To Whom? Region 2 OCD by phone (Mike Bratcher) Date and Hour: U0/20/2013 ...

If YES, Volume Impacting the Watercomplete Watercomplet By Whom? Jim Heap Was a Watercourse Reached? ☐ Yes 🛛 No If a Watercourse was Impacted, Describe Fully.\* JUL **03** 2013 NMOCD ARTESIA Describe Cause of Problem and Remedial Action Taken.\* CAUSE: The 1002 Line was over-pressured due to a processing shut-down downstream; the South Carlsbad Compressor Station shut-down on highliquid load. A pressure relief valve activated to relieve the pressure build-up. ACTION: An operational technician attended the relief event and determined the valve has closed properly. Describe Area Affected and Cleanup Action Taken.\* All gas was lost to atmosphere. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: Approved by Environmental Specialist: Printed Name: Matthew E. Marra AUG

Approval Date:

Conditions of Approval:

/-/-70/3 Phone: 713.381.6595 Attach Additional Sheets If Necessary

E-mail Address: memarra@eprod.com

Title:

FJMW 1322553318 iJMW 1322554252

Senior Director, Environmental

ZRP-1822

Attached \[ \]

Expiration Date:



July 1, 2013

7012 1010 0001 3760 6690 Return Receipt Requested

Mr. Mike Bratcher New Mexico Oil Conservation Division District 2 Office 811 South First Street Artesia, New Mexico 88210

RE:

Form C-141 Report

1002 Gathering Line Release

Mr. Bratcher

Enclosed, please find the requisite C-141 Form for the unplanned release on our 1002 gathering line in Eddy County on June 27-28, 2013. This is sent pursuant to 29 (19.15.29) NMAC and as follow-up to verbal notification made to you by phone on, June 28, 2013.

If you have any questions or need more information, please contact Jim Heap by phone at 432-686-5404, by email at jkheap@eprod.com or me at 713-318-6684

Regards,

Matthew E. Marra,

Senior Director, Environmental

/sjn attachments

RECEIVED

JUL 03 2013

NMOCD ARTES'A

JUL 03 20 OCD AF