


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 1323129239

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Enterprise Field Services LLC	Contact	Jim Heap
	PO Box 4324, Houston, TX 77252	Telephone No.	432-686-5404
Facility Name	Pipeline ROW, Zircon Lateral	Facility Type:	Gas Gathering Pipeline
Surface Owner	Multiple Owners	Mineral Owner	NA
		Lease No.	NA

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	14	19S	29E					Eddy

Latitude 32.653682 N Longitude -104.052034 W

NATURE OF RELEASE

Type of Release	Natural Gas	Volume of Release	50 MCF	Volume Recovered	0
Source of Release	Pipeline Blow Down to repair leaking valve.	Date and Hour of Occurrence	12-07-2012 12:10 hrs (MST)	Date and Hour of Discovery	12-07-2012 13:00 hrs (MST)
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			


If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The pipeline was vented to atmosphere to repair a valve that began leaking when exercised.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:			
Printed Name: Matthew E. Marra	Approved by District Supervisor: Accepted for record NMOC D		
Title: Senior Director, Environmental	Approval Date: AUG 19 2013	Expiration Date:	
E-mail Address: memarra@eprod.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date:	Phone: 713-381-6684		

* Attach Additional Sheets If Necessary

fJMW 1323129097

iJMW 1323129426


2 RP-1843



ENTERPRISE PRODUCTS PARTNERS L.P.
ENTERPRISE PRODUCTS HOLDINGS LLC
(General Partner)

ENTERPRISE PRODUCTS OPERATING LLC

December 13, 2012



7012 2210 0001 2251 3221
Return Receipt Requested

Mr. Mike Bratcher
New Mexico Oil Conservation Division
District 2 Office
811 South First Street
Artesia, New Mexico 88210

**RE: Form C-141 Report for Enterprise Products
Zircon Lateral Line Blow-down Release**

Mr. Bratcher:

Pursuant to 29 (19.15.29) NMAC please find enclosed the requisite C-141 Form for the blow down release on our Zircon Lateral gathering line in Eddy County. The blow down was completed to a leaking valve.

If you have any questions or need more information, please contact Jim Heap by phone at 432-686-5404, by email at jkheap@eprod.com or me at 713-318-6684

Regards,

A handwritten signature in black ink, appearing to be "M. Marra".

Matthew E. Marra
Senior Director, Environmental

/sjn
attachments