

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**JMW 1323135377** **OPERATOR** ☐ Initial Report ☒ Final Report

Name of Company	Enterprise Field Services LLC <b>1000347</b>	Contact	Jim Heap
	PO Box 4324, Houston, TX 77252	Telephone No.	432-686-5404
Facility Name	Pipeline ROW, Trunk A Separator <b>#2</b>	Facility Type:	Gas Gathering Pipeline
Surface Owner	Multiple Owners	Mineral Owner	NA
		Lease No.	NA

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	12	23S	27E					Eddy

**Latitude:** N 32.313368 **Longitude:** W -104.135395

**NATURE OF RELEASE**


Type of Release	Natural Gas, H2S Contaminated	Volume of Release	165 MCF	Volume Recovered	0
Source of Release		Date and Hour of Occurrence		Date and Hour of Discovery	
Purge activities to clear H2S from line.		02-25-2013 12:00 MST (start)		02-25-2013 12:15 MST (end)	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A third-party well connected to the Enterprise Gathering system introduced high H2S gas to the system. To eliminate this gas, the gathering lines needed to be purged. Volume includes the gathering line and station residual volumes.					
Describe Area Affected and Cleanup Action Taken.*					
Line was purged to reduce the H2S level at the South Carlsbad Compressor Station below the permitted limit of 4 ppm.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		<b>OIL CONSERVATION DIVISION</b>			
Printed Name: Matthew E. Marra		Approved by District Supervisor: <b>Accepted for record NMOCD</b>			
Title: Senior Director - Environment		Approval Date: <b>AUG 19 2013</b>		Expiration Date:	
E-mail Address: memarra@eprod.com		Conditions of Approval:		Attached <input type="checkbox"/>	
Date: <b>3-1-2013</b> Phone: 713-381-6684					

\* Attach Additional Sheets If Necessary

**JMW 1323130690**

**JMW 1323136709**

**2RP-1845**



Enterprise  
Products


ENTERPRISE PRODUCTS PARTNERS L.P.  
ENTERPRISE PRODUCTS HOLDINGS LLC  
(General Partner)

ENTERPRISE PRODUCTS OPERATING LLC

March 1, 2013

7012 2920 0001 7977 2343  
Return Receipt Requested

Mr. Mike Bratcher  
New Mexico Oil Conservation Division  
District 2 Office  
811 South First Street  
Artesia, New Mexico 88210



**RE: Form C-141 Reports**  
**Various Purge Releases Performed February 25 and February 26, 2013**

Mr. Bratcher:

Enclosed please find 3 C-141 Forms for the following releases.

2.824 MMCF from the Trunk A Separator purge in Eddy County, performed 02/25/2013  
0.165 MMCF from the Trunk A Separator purge in Eddy County, performed 02/25/2013  
0.239 MMCF from the Trunk A Separator purge in Eddy County, performed 02/26/2013

These are being sent pursuant to 29 (19.15.29) NMAC and as follow-up to Jim Heap's verbal notification to you of the initial purge event. The H2S has been completely purged from the Carlsbad Gathering System lines and appropriate equipment is in-place in the field to eliminate high H2S from the identified wells from reaching the South Carlsbad Compressor Station.

If you have any questions or need additional information, please contact our area field representative, Jim Heap, at 432-696-5404 ([jkheap@eprod.com](mailto:jkheap@eprod.com)) or me directly at 713-381-6684.

Yours truly,

Matthew E. Marra  
Sr. Director - Environmental

/sjn  
attachments