

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW 1323241466

Name of Company Enterprise Field Services LLC <i>1000347</i>		Contact Jim Heap
PO Box 4324, Houston, TX 77252		Telephone No. 432-686-5404
Facility Name Pipeline ROW, Line A6 <i>2</i>	Facility Type: Gas-Gathering Pipeline	
Surface Owner	Mineral Owner NA	Lease No. NA


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	14	25S	25E					Eddy

Latitude: N 32.134822 Longitude: W -104.363991

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release 339 MCF	Volume Recovered 0
Source of Release Pipeline Blow-down to relieve hydrate blockage.	Date and Hour of Occurrence (Start) 02-07-2013 07:30 MST	Date and Hour of Discovery (End) 02-07-2013 08:00
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The affected section of the 6-inch line was isolated and blown-down to relieve a hydrate blockage.		
Describe Area Affected and Cleanup Action Taken.*		



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>		OIL CONSERVATION DIVISION	
Printed Name: Matthew E. Marra		Approved by District Supervisor: Accepted for record NMOCD	
Title: Senior Director, Environmental	Approval Date: AUG 20 2013	Expiration Date:	
E-mail Address: memarra@eprod.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: <i>2-12-2013</i> Phone: 713-381-6684			

* Attach Additional Sheets If Necessary

fJMW 1323240435

iJMW 1323241662


2RP-1851



ENTERPRISE PRODUCTS PARTNERS L.P.
ENTERPRISE PRODUCTS HOLDINGS LLC
(General Partner)

ENTERPRISE PRODUCTS OPERATING LLC

February 12, 2013



7012 2210 0001 2197 3033
Return Receipt Requested

Mr. Mike Bratcher
New Mexico Oil Conservation Division
District 2 Office
811 South First Street
Artesia, New Mexico 88210

**RE: Form C-141 Report
Gas Loss Reported in the Carlsbad Gathering Field**

Mr. Bratcher:

Pursuant to 29 (19.15.29) NMAC please find enclosed the requisite C-141 Form for the following release found on our B6 Gathering Line in our Carlsbad Gathering Field, Eddy County.

The release was discovered during a full-line inspection associated with the repair of a previously reported leak and blow-down on the same line.

If you have any questions or need more information, please contact Jim Heap by phone at 432-686-5404, by email at jkheap@eprod.com or me at 713-318-6684

Regards,

Matthew E. Marra
Senior Director, Environmental

/sjn
attachments