

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JUN 28 2013

NMOCD ARTESIA

Form C-141
Revised August 8, 2011

Submit Copy to Appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW1324652889

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Chevron USA Inc. 4323	Contact	David A. Pagano
Address	15 Smith Rd., Midland, TX, 79705	Telephone No.	wk: 575-396-4414X275 cell: 505-787-9816
Facility Name	Skelly 907 BTY	Facility Type	Oil Production Battery
Surface Owner	Federal BLM	Mineral Owner	Federal
		API No.	

SKU 907 BTY (CTB) - Latitude: 32.819634 / Longitude: -103.872881

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	22	17S	31E					Eddy

NATURE OF RELEASE

Type of Release	Flare	Volume of Release	396 MCF	Volume Recovered	0 MSCF
Source of Release	Flare	Date and Hour of Occurrence	06/26/13 8:00AM	Date and Hour of Discovery	06/26/13 8:00AM
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.* N/A					
Describe Cause of Problem and Remedial Action Taken.* Operations shut in sales line to reduce risk while rig crossed over road crossing in route to well location. Once rig safely moved over road crossing operations returned opened sales line and flaring stopped.					
Describe Area Affected and Cleanup Action Taken.* N/A					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature:	OIL CONSERVATION DIVISION Accepted for record NMOCD				
Printed Name:	David A. Pagano	Approved by Environmental Specialist:			
Title:	Health & Environmental Specialist	SEP 03 2013		Approval Date:	
E-mail Address:	dpgn@chevron.com	Expiration Date:			
Date:	06/28/13	Conditions of Approval:			Attached <input type="checkbox"/>
Phone:	505-787-9816				

* Attach Additional Sheets If Necessary

fJMW132113121

iJMW1324653158

2RP-1889

Bratcher, Mike, EMNRD

From: Pagano, David (David.Pagano) <David.Pagano@chevron.com>
Sent: Friday, June 28, 2013 7:16 AM
To: Pagano, David (David.Pagano); Bratcher, Mike, EMNRD
Cc: Moschetti, Nick (NMOS); DeLeon, Josepha
Subject: Final C141 report for flaring at SKU 907 on 6/26/13
Attachments: 20130626 C-141 Skelly 907 Bty Flare FS.pdf

Mike,

Here is the final report for the flaring at our Skelly 907 Battery on 6/26/13 when the sales line was shut in so that a rig could safely move over the line in route to a new location.

Regards,

David A. Pagano

MCA Health & Environmental Specialist (Central Permian – Vacuum/Buckeye, Dollarhide & Sundown)

56 Texas Camp Rd., Lovington, NM 88260

☎ Phone: 575-396-4414 x275

☎ Cell: 505-787-9816

☎ Fax: 575-396-6913

dpgn@chevron.com

"CONFIDENTIALITY NOTICE: This message is confidential and may be privileged. If you believe that this email has been sent to you in error, please reply to the sender that you received the message; then please delete this email."