
							Г	RE	CE	IVE	5			
District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410				Energy Mir Oil C	vation Div	l Resourc	PS		7 2013 ARTES	BIA to appr	opriate Di	Form C-141 Detober 10, 2003 strict Office in 0.15.29 NMAC		
District IV 1220 S. St. France	cis Dr., Santa	ı Fe, NM 87505				St. Franc NM 875								
Release Notification and Corrective Action														
nJMW 132,6341736 OPERATOR Initial Report I Final Report														
	mpany: Li	nn Operatin	s 20	09324		Contact: Bri								
Address: 2130 W. Bender Hobbs, NM 88240Telephone No.: 575-738-1739Facility Name: HE West B 50Facility Type: Oil Producer														
Surface Owner: Federal Mineral Owner:														
							FÁSE			7111110				
Unit Letter	Section	Township	Range	Feet from the		h/South Line Feet from the East/West Line County								
N	03	175	31Ē	50	S	South	1400	)	W	est		Ede	ły	
	I			Latitude: 32	85653	Longitud	e• -103 8(	5094			1			
Latitude: 32.85653 Longitude: -103.86094 NATURE OF RELEASE														
Type of Rele	ase: Produc	ed Water / Oi	1		UKE	Volume of		.5bbls/ .5	bbl	Volume F	Recover	ed: 0 / 0		
Source of Release: 3" poly pipeline						Date and Hour of Occurrence:Date and Hour of Discovery:09/09/20132:30pm09/09/2013							y:	
Was Immediate Notice Given?					• •	If YES, To			ł	071071201	15 2.50	<u>pin</u>		
By Whom?			Yes 🗵	No 🗌 Not Ro	quirea	Date and F	lour							
Was a Water	course Read					If YES, Volume Impacting the Watercourse.								
If a Watercourse was Impacted, Describe Fully.*:														
Describe Cau	se of Proble	em and Reme	dial Actio	n Taken *· Receiv	red call t	hat nickun di	iven hv Fe	rauson Pi	ineline	Construc	tion em	nlovee had	driven off of	
Describe Cause of Problem and Remedial Action Taken.*: Received call that pickup driven by Ferguson Pipeline Construction employee had driven off of road to get around truck performing pressure test on new pipeline. While crossing flowline undercarriage of pickup punctured hole in flowline for West B #50 well causing spill. Approx 6 barrels fluid released onto road and just off of road. Combination of oil and water. Approx 5.5 bbl water and .5 bbl oil.														
Shut in well.				leased onto road a	na jusi c	on of road. C	ombination	i oi oii an	id wate	er. Approx	5.5 00	i water and	1.5 001 011.	
Describe Area Affected and Cleanup Action Taken.* : about 100ft x 50ft area affected. Remedial action pending.														
beside Area Areated and Cleanup Action raken about roon x son area arrected. Remedial action pending.														
I hereby certi	fy that the i	nformation gi	ven above	e is true and comp	lete to th	ne best of my	knowledge	e and und	erstan	d that purs	suant to	NMOCD	rules and	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability														
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other														
federal, state,							e the opera	uor of res	ponsit	onity for c	ompilai	ice with a	iy other	
	N	//					<u>OIL (</u>	CONSE	ERV	ATION	DIVI	SION		
Signature: Store all														
Printed Name: Brian Wall				·	Approved by District Supervisor: Signed By Mile Bematcon Approval Date: Expiration Date:									
Title: Construction Foreman II						S Approval Da	EP 20	2013	E	xpiration	Date:			
E-mail Address: bwall@linnenergy.com														
Date: 09/16/2013 Phone: 806-367-0645						Remediation per OCD Rule & Guidelines, &								
Attach Additional Sheets If Necessary					1	like approval by BLM. SUBMIT REMEDIATION 2RP-1919								
					-	Oct	ober	- 20	$\mathcal{D}_{\mathcal{L}}$	2013	5		111	

## Bratcher, Mike, EMNRD

From: McCracken, Theresa <TMcCracken@linnenergy.com> Sent: Tuesday, September 17, 2013 7:46 AM mburton@blm.gov; Bratcher, Mike, EMNRD Wall, Fred; mistyh@fergusoncc.com Linn- HE West B #50 9-9-13 Subject: **Attachments:** West B # 50 9-9-13.pdf



Attached is the initial C-141 for the above referenced location. Please contact Ferguson Construction, Misty Hein @ 575-396-3689. They will be handling the clean up.

Thank you,

To:

Cc:



## Theresa McCracken

Field Administrator LINN Energy, LLC 2130 W Bender Hobbs, NM 88240 T: 575-738-1739 / F: 575-738-1740 tmccracken@linnenergy.com

This electronic message, together with any attachments, contains information from LINN Energy that may be confidential and intended solely for the use of the addressee only. If you are not the intended recipient, please note that any disclosure, dissemination, distribution or copying of this message, or any attachment, is strictly prohibited. Also, please notify the original sender by return e-mail and delete the message, along with any attachments, from your computer. Finally, the recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.

## Bratcher, Mike, EMNRD

From:		Bratcher, Mike, EMNRD
Sent:		Tuesday, September 17, 2013 2:51 PM
То:	5	'McCracken, Theresa'; mburton@blm.gov
Cc:	•	Wall, Fred; mistyh@fergusoncc.com
Subject:		RE: Linn- HE West B #50 9-9-13

Theresa,

From a regulatory standpoint, Linn is the responsible party in instances like this. If Ferguson has agreed to perform remediation, that's OK, but they need to contact Mike Burton w/BLM and me to coordinate the work. Clean-up will have to be by an approved (BLM & OCD) remediation plan.

Thanks,

Mike Bratcher NMOCD District 2 811 S. First Street Artesia, NM 88210 O: 575-748-1283 X108 C: 575-626-0857 F: 575-748-9720 mike.bratcher@state.nm.us

From: McCracken, Theresa [mailto:TMcCracken@linnenergy.com]
Sent: Tuesday, September 17, 2013 7:46 AM
To: mburton@blm.gov; Bratcher, Mike, EMNRD
Cc: Wall, Fred; mistyh@fergusoncc.com
Subject: Linn- HE West B #50 9-9-13

Attached is the initial C-141 for the above referenced location. Please contact Ferguson Construction, Misty Hein @ 575-396-3689. They will be handling the clean up.

i

Thank you,



Theresa McCracken

1

Field Administrator LINN Energy, LLC 2130 W Bender Hobbs, NM 88240 T: 575-738-1739 / F: 575-738-1740 tmccracken@linnenergy.com

This electronic message, together with any attachments, contains information from LINN Energy that may be confidential and intended solely for the use of the addressee only. If you are not the intended recipient, please note that any disclosure, dissemination, distribution or copying of this message, or any attachment, is strictly prohibited. Also, please notify the original sender by return e-mail and delete the message, along with any attachments, from your computer. Finally, the recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.

## Bratcher, Mike, EMNRD

From:	Chavez, Carl J, EMNRD
Sent:	Thursday, September 12, 2013 11:16 AM
То:	Dade, Randy, EMNRD; Bratcher, Mike, EMNRD
Cc:	Sanchez, Daniel J., EMNRD; VonGonten, Glenn, EMNRD
Subject:	Loco Hills Release: Ferguson Construction Co. (Lovington) was working for Apache Co. when truck ran over Linn Energy 3 inch Poly Line w/ Crude Oil (~ 5 - 6 bbls)

Randy and Mike:

FYI: I just received a call from Cynthia with Ferguson Construction (575) 396-3689. One of their workers ran over a 3 inch poly line with crude oil in the Loco Hills area on  $9/9/13 \sim 14:30$ . The line was owned by Linn Energy and the location was referred to as the West B-50 Spill. She called for instructions on completion of a C-141 Form, location to send it, and indicated that the spill has been cleaned up. In case you get a call, etc.

Thanks.

Carl J. Chavez, CHMM New Mexico Energy, Minerals & Natural Resources Department Oil Conservation Division, Environmental Bureau 1220 South St. Francis Drive, Santa Fe, New Mexico 87505 Office: (505) 476-3490 E-mail: <u>Carl J. Chavez@State.NM.US</u> Website: <u>http://www.emnrd.state.nm.us/ocd/</u> "Why Not Prevent Pollution; Minimize Waste; Reduce the Cost of Operations; & Move Forward With the Rest of the Nation?" To see how, please go to: "Pollution Prevention & Waste Minimization" at

http://www.emnrd.state.nm.us/ocd/environmental.htm#environmental