

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 1327050662

OPERATOR Initial Report Final Report

Name of Company <i>OXY USA WTP LP 110696</i>	Contact BERNAL, THOMAS
Address 329 Marathon Rd, Lakewood	Telephone No. (575) 628-4112
Facility Name INDIAN BASIN GAS PLANT	Facility Type GAS PROCESSING PLANT

Surface Owner	Mineral Owner INDIAN BASIN	Lease No.
---------------	----------------------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy

Latitude 32°27'52.502" Longitude 104°34'28.004"

NATURE OF RELEASE

Type of Release Gas	Volume of Release 170.73 MCF	Volume Recovered 0
Source of Release Acid Gas Flare	Date and Hour of Occurrence 6/21/2011 5:48:00 PM	Date and Hour of Discovery 6/21/2011 5:48:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*	<div style="border: 2px solid black; padding: 5px; width: fit-content; margin: auto;"> <p>RECEIVED</p> <p>JUN 27 2011</p> <p>NMOCD ARTESIA</p> </div>	

Describe Cause of Problem and Remedial Action Taken.*
Cause:
ACID GAS COMPRESSOR SHUT DOWN ON SECOND STAGE HIGH DIFFERENTIAL PRESSURE SHUTDOWN. WE ARE STILL TROUBLESHOOTING THE COMPRESSOR TO DETERMINE THE ROOT CAUSE.
Remedial Action Taken:
CALLED OFF SHIFT PERSONNEL TO START WARMING THE SULPHUR PLANT UP IN ORDER FOR IT TO BE PLACED ONLINE IN THE EVENT THAT THE ACID GAS COMPRESSOR CANNOT BE RESTARTED. ALSO CALLED OFF SHIFT PERSONNEL TO HELP TROUBLESHOOT THE COMPRESSOR IN ORDER TO FIND THE ROOT CAUSE.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Clint Kirkes</i>	OIL CONSERVATION DIVISION	
Printed Name: Clint Kirkes	Approved by District Supervisor:	Accepted for record NMOCD
Title: <i>Plant Specialist</i>	Approval Date: SEP 27 2013	Expiration Date:
E-mail Address: clinton_kirkes@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>6/22/2011</i>	Phone: 575-628-4113	

* Attach Additional Sheets If Necessary
FJMW 1327034125 *iJMW 1327052350* *ZRP-1946*