

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*nJMW 1327054708*

**OPERATOR**  Initial Report  Final Report

Name of Company OXY USA WTP LP <i>160696</i>	Contact BERNAL, THOMAS
Address 329 Marathon Rd, Lakewood	Telephone No. (575) 628-4112
Facility Name INDIAN BASIN GAS PLANT	Facility Type GAS PROCESSING

Surface Owner	Mineral Owner INDIAN BASIN	Lease No.
---------------	----------------------------	-----------

**LOCATION OF RELEASE**

Unit Letter G	Section 23	Township 21-S	Range 23-E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	----------------

Latitude 32°27'52.502" Longitude 104°34'28.004"

**NATURE OF RELEASE**


Type of Release Gas	Volume of Release 96.2 MCF	Volume Recovered 0
Source of Release Residue Flare	Date and Hour of Occurrence 7/26/2011 11:23:00 AM	Date and Hour of Discovery 7/26/2011 11:23:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Cause:  
FLARED RESIDUE GAS STREAM 5 MINUTES ON HIGH OXYGEN CONTENT.  
Remedial Action Taken:  
CONTACTED OXY MEASUREMENT PERSONNEL TO AID IN LOCATING THE SOURCE OF THE OXYGEN. PLANT OPERATIONS STARTED TO TEST THE INLET GAS GATHERING LINES TO TRY AND DETERMINE THE SOURCE.

Describe Area Affected and Cleanup Action Taken.\*  
N/A



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Clint Kirkes</i>	<b>OIL CONSERVATION DIVISION</b> Accepted for record <b>NMOCD</b>	
Printed Name: Clint Kirkes	Approved by District Supervisor:	
Title: <i>Plant Specialist</i>	Approval Date: <b>SEP 27 2013</b>	Expiration Date:
E-mail Address: clinton_kirkes@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>7-27-2011</i> Phone: 575-628-4113		

\* Attach Additional Sheets If Necessary

*FJMW 1327034125*

*iJMW 1327055064*

*ZRP-1948*