District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division

SEP 3 0 2013

RECEIVED

Form C-141 Revised October 10, 2003

NMOCD ARTES Desired 2 Copies to appropriate

with Rule 116 on back

1220 South St. Francis Dr. 1220 S. St. Francis Dr., Santa Fe, NM 87505 side of form Santa Fe, NM 87505 **Release Notification and Corrective Action OPERATOR** Initial Report Final Report COG OPERATING LLC 229137 Robert McNeill Name of Company Contact 432-230-0077 600 West Illinois Avenue, Midland, TX 79701 Address Telephone No. **Facility Name** Sly Hawk State #005 Facility Type Main line Surface Owner State Mineral Owner Lease No. (API#) 30-015-35103 LOCATION OF RELEASE Unit Letter Section North/South Line Feet from the East/West Line County Township Range Feet from the Eddy 25S 28E Α Latitude 32 09.982 Longitude 104 04.068 NATURE OF RELEASE Type of Release Produced water Volume of Release 70bbls Volume Recovered Obbls Source of Release Main water line Date and Hour of Occurrence Date and Hour of Discovery 09-22-2013 09-22-2013 12:30pm Was Immediate Notice Given? If YES, To Whom? Mike Bratcher - NMOCD By Whom? Michelle Mullins Date and Hour 09-25-2013 3:43pm Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. Yes No If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* Fuse failed on polyline. Fuse line back together. Describe Area Affected and Cleanup Action Taken,* Initially an estimated 70bbls were released due to a fuse came apart on a polyline. We were unable to recover any fluids. The spill was on the North and South side of the road. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a work plan to the NMOC for approval prior to any significant remediation work. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: Approved by District Supervisorigned By Printed Name: Robert Grubos Jr. Approval QCT. 02 2013 Title: Senior Environmental Coordinator **Expiration Date:**

Attach Additional Sheets If Necessary

09-30-2013

rgrubbs@concho.com

Phone:

432-661-6601

E-mail Address:

Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION

Conditions of Approval:

PROPOSAL NO LATER THAN:

Attached

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>


Sent: Monday, September 30, 2013 2:21 PM

To: Bratcher, Mike, EMNRD

Cc: Robert McNeill; Tavarez, Ike; Kujawski, Marcus (Marcus.Kujawski@tetratech.com)

Subject: C-141 Initial Report - Sly Hawk State #005

Attachments: Sly Hawk State #005(Mainline) -- Date of Release -- 09-22-2013.pdf




Mr. Bratcher,

Please see attached the C-141 Initial Report for a release that occurred at our Sly Hawk State #005 (Mainline) on 09-22-2013 in Eddy County New Mexico.

We plan to assess the spill area timely.

Thank you,

Robert Grubs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com
Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



Bratcher, Mike, EMNRD

From:

Michelle Mullins < MMullins@concho.com>

Sent:

Wednesday, September 25, 2013 2:43 PM

To:

Bratcher, Mike, EMNRD

Cc: Subject:

Sly Hawk State #5-Immediate Notification

Follow Up Flag:

Follow up

Robert Grubbs

Flag Status:

Completed

Mr. Bratcher:

At approximately 12:30 p.m. on 9/22/2013, a produced fluid release was discovered near the above-referenced facility. An estimated 70 barrels of produced fluid was released. The cause of the release is currently under investigation. We will follow up within 15 days with a C-141 Report. GPS coordinates, legal description and driving directions are listed below.

32 09.982 104 04.068

Sly Hawk State #5 (nearest well) Sec 3 T25S R28E Eddy County, NM API 30-015-35103

From Highway 285, travel south towards Pecos. At Mile Marker 12, turn east. Travel approximately .25 miles to release point on south side of road.

Michelle Mullins HSE Field Technician COG Operating, LLC (432) 934-1052 mmullins@concho.com

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.