
District I · · · State					of New Mexico			
1(25 M Essent De Halte ND (20240								
District II 811 S. First St.,	Artesia, NM	88210		Lifergy Willera	rals and Natural Resources Form C-141 Revised August 8, 2011			
District III Oil Con					servation Division	AT 91 2013 S	i ubmit 1 Copy to appr	onriate District Office in
1000 Rio Blazos Road, Aziec, NM 8/410				servation Division 2 1 2013 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.				
1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa					Fe, NM 87505 ARTESIA			
Release Notification and Corrective Action								
NJW	N132	2953	500	-2-	OPERATOR		N Initial Report	Final Report
Name of Company		Centurion Pipeline LP 270593			Contact	BECKY MOORE		
Address		P O Box 51790 Midland, TX 79710			Telephone No.	432-686-6805		
Facility Name		Artesia - Saunders			Facility Description	on Artesia to Wasson 10"		
Surface Owner		New Mexico State Minera Land		Mineral Owner		API No.		
LOCATION OF RELEASE								
Unit Letter	Section 24	Township 17S	Range 28E	Feet from the	North/South Line	Feet from the	East/West Line	County EDDY
		L	Latitude	32.82500	Longitude	-104.12275	I	
NATURE OF RELEASE								
Type of Release		Sweet Crude Oil		Volume of Release		Volume Recovered	40 BARRELS	
Source of Release		EQUIPMEN FAILURE	IPMEN Date and Hour of Occurrence:		10/14/13 11:00AM	Date and Hour o	f Discovery:	Oct 14, 2013 11:00 AM
Was Immedia	te Notice G	iven?	Yes	No 🚺 Not Required	If YES, To Whom?	Mike Bra	atcher via.	Voice mail on
By Whom?		BECKY MOORE			Date and Hour 10/14/13 3:30 pm 3:30pm 4 Cell phone #			
Was a Waterc	ourse Reac	ched? Yes No			If YES, Volume Impacting the Watercourse.			
If a Watercour N/A	rse was Imp	pacted, Descril	be Fully.*		•			
Describe Cause of Problem and Remedial Action Taken.								
Discovered check valve leak and immediately shut line down. Emergency One-Call made and permanent repair. Valve check replaced. MP96. Source of leak was isolated and the remote site secured.								
Describe Area Affected and Cleanup Action Taken.								
Majority of crude was contained within tin horn containment. Vacuum trucks immediately mobilized to site and recovered 40 Bbls. Remaining stained soil								
will be excavated and managed according to OCD required remedial action plans. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and								
		-		d/or file certain release r	•	-	-	
				C-141 report by the NMC			-	
operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state,								
or local laws a			ceptance c	a C-141 report does no	st reneve the operator	of responsionity 1	for compnance with a	ny other rederal, state,
Signature:					OIL CONSERVATION DIVISION #			
Printed Name:		BECKY MOORE			OIL CONSERVATION DIVISION Signed By MILTA Demonstrate			
Title:		COMPLIANCE COORDINATOR				2 2 2013	Expiration Date:	and the second secon
E-mail Addre	Address: Rebecca_Moore@oxy.com		Conditions of Appro	oval:	· · · · · · · · · · · · · · · · · · ·	Attached:		
Date: 10/17/2013 Phone: 432-686-6805					Remediation per OCD Rule &			
* Attach Addi	tionakShaa			<u> </u>	Guidelines. SUB		ATION	20 0-15
£JM	WI:	3295 3295	534	4882 _	November	NO LATER THA	aiv: 21 D	29-2015
ijm	\mathcal{M}	3295	536:	342				



P.O. Box 51790 Midland, Texas 79710 Phone (432) 686-1482 Fax (432) 686-1425

October 17, 2013

New Mexico Oil Conservation Division Dist 2 811 S First St. Artesia, New Mexico 88210

> Leak located at referenced Legal Description: Section: 24, Township: 17S, Range: 28E EDDY County, NEW MEXICO Centurion Leak Number CP55034757

Attached for further handling, is the NMC141 pertaining to the leak that occurred on 10/14/13 in, Section: 24, Township: 17; Range: 28E. Any correspondence regarding this leak needs to be directed to Centurion Pipeline L.P.; P.O. Box 51790; Mid TX 79710; Phone (432) 686-1482 or Fax (432) 686-1425.

If further information is required, please advise.

Sincerely,

pre

BECKY MOORE COMPLIANCE COORDINATOR 432-686-6805

Attachments