

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED

OCT 29 2013

INWOOD ARTESIA

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Linn Energy	269324	Contact	Brian Wall
Address	2130 W. Bender Blvd., Hobbs, NM 88240		Telephone No.	(806) 367-0645
Facility Name	J.L. Keel A #11		Facility Type	Injection Line Release
Surface Owner	BLM	Mineral Owner	API No. 3001505099	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	7	17S	31E	1945	FNL	762	FEL	Eddy

Latitude 32°51'3.227"N Longitude 103°54'10.98"W

NATURE OF RELEASE

Type of Release	Production water	Volume of Release	100 bbls	Volume Recovered	15 bbls
Source of Release	Injection Line	Date and Hour of Occurrence	8/22/11	Date and Hour of Discovery	8/22/11
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Terry Gregston - BLM		
By Whom?	Date and Hour		8/22/11		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The injection line to the injection well ruptured at the buried 'T' intersection affecting 12,383 sq ft of pasture land. A total of 100 bbls of produced water was released and a total of 15 bbls of produced water was recovered.

Describe Area Affected and Cleanup Action Taken.*

The site will be assessed vertically and horizontally and a Corrective Action Plan will be written with recommendations to remediate the site.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <u>Fred B Wall</u>	Approved by Environmental Specialist:	
Printed Name: Brian Wall	Signed By <u>Mike Brandon</u>	
Title: Construction Foreman II	Approval Date: OCT 29 2013	Expiration Date:
E-mail Address: Bwall@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	Phone: (806) 367-0645	Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:

* Attach Additional Sheets If Necessary

November 29, 2013

2RP-2031

Warren, JeanMarie, EMNRD

From: Lara Weinheimer <lweinheimer@rice-ecs.com>
Sent: Tuesday, October 29, 2013 9:54 AM
To: 'Burton, Michael'; Bratcher, Mike, EMNRD
Cc: Warren, JeanMarie, EMNRD; 'Hack Conder'; 'Jacob Kamplain'; 'Wall, Fred'
Subject: Initial C-141 for the Linn J.L. Keel A
Attachments: Linn J L Keel A #11 Initial C-141-signed.pdf

Attached is the initial C-141 for the Linn J.L. Keel A #11 release. If you have any questions, let us know.

Thanks!

Lara Weinheimer
Rice Environmental Consulting & Safety
Project Scientist
419 West Cain
Hobbs, NM 88240
(575) 441-0431