

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

nJMW 1333830613		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company OXY USA WTP LP 16696		Contact CAMPBELL, RODNEY			
Address 329 Marathon Rd, Lakewood		Telephone No. (575) 628-4167			
Facility Name INDIAN BASIN GAS PLANT		Facility Type GAS PROCESSING FACILITY			
Surface Owner		Mineral Owner INDIAN BASIN		Lease No.	


LOCATION OF RELEASE

Unit Letter G	Section 23	Township 21-S	Range 23-E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	----------------

Latitude 32°27'52.502" Longitude 104°34'28.004"

NATURE OF RELEASE

Type of Release Gas	Volume of Release 256.7 MCF	Volume Recovered 0
Source of Release Residue Flare	Date and Hour of Occurrence 11/11/2013 4:25:00 PM	Date and Hour of Discovery 11/11/2013 4:25:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Cause: OXY INDIAN BASIN GAS PLANT FLARED RESIDUE SALES GAS FOR 10 MINUTES DUE TO HIGH OXYGEN CONTENT IN SALES GAS FLOW. Remedial Action Taken: OPERATIONS SAMPLED STABILIZER COMPRESSOR DISCHARGE METER WITH A PORTABLE OXYGEN ANALYZER.		
Describe Area Affected and Cleanup Action Taken.* N/A		



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: RODNEY CAMPBELL		Approved by District Supervisor Signed By	
Title: HES Specialist	Approval Date: DEC 04 2013	Expiration Date:	
E-mail Address: RODNEY_CAMPBELL@OXY.COM	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 11-21-13	Phone: (575) 628-4167		

\* Attach Additional Sheets If Necessary

Like approval by  
BLM

2RP- 2093

fJMW 1327034125  
IJMW 1333832609