

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED DEC 16 2013 NMOCD ARTESIA	Form C-141 Revised October 10, 2003
	Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

NAME <u>NJM/1335256451</u>		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company <u>COG OPERATING LLC 229137</u>		Contact <u>Robert McNeill</u>			
Address <u>600 West Illinois Avenue, Midland, TX 79701</u>		Telephone No. <u>432-230-0077</u>			
Facility Name <u>Loco Hills SWD 33 #004</u>		Facility Type <u>Tank Battery</u>			
Surface Owner <u>Federal</u>		Mineral Owner		Lease No. (API#) <u>30-015-37269</u>	

LOCATION OF RELEASE

Unit Letter P	Section 33	Township 17S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	-----------------------

Latitude 32.78607

Longitude 103.97054

NATURE OF RELEASE

Type of Release <u>Produced water</u>	Volume of Release <u>10bbls</u>	Volume Recovered <u>9bbls</u>
Source of Release <u>Steel flowline</u>	Date and Hour of Occurrence <u>12-05-2013</u>	Date and Hour of Discovery <u>12-05-2013 08:00am</u>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* <u>A steel flowline developed a hole due to corrosion. Replaced the steel line.</u>		
Describe Area Affected and Cleanup Action Taken.* <u>Initially 10bbls of produced water were released. A hole developed in a steel flowline. We were able to recover 9bbls with a vacuum truck. All free fluids have been recovered. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for approval prior to any significant remediation work.</u>		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
SIGNATURE <u>Robert Grubbs Jr.</u> Printed Name: <u>Robert Grubbs Jr.</u> Title: <u>Senior Environmental Coordinator</u> E-mail Address: <u>rgrubbs@concho.com</u> Date: <u>12-11-2013</u> Phone: <u>432-661-6601</u>		OIL CONSERVATION DIVISION Approved by District Supervisor: <u>Mike Brannon</u> DEC 18 2013 Approval Date: <u>DEC 18 2013</u> Expiration Date: Conditions of Approval: <u>Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION</u> Attached <input type="checkbox"/>


* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:
January 18, 2013

2RP-2116

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Monday, December 16, 2013 7:50 AM
To: Bratcher, Mike, EMNRD; Mike Burton (mburton@blm.gov) (mburton@blm.gov); Amos, James <jamos@blm.gov> (jamos@blm.gov)
Cc: Robert McNeill; Tavaréz, Ike; Kujawski, Marcus (Marcus.Kujawski@tetrattech.com)
Subject: C-141 Initial Report - Loco Hills SWD 33 #004
Attachments: Loco Hills SWD 33 #004 (SWD) Date of Release 12-05-2013.pdf



Gentlemen,

Please see attached the C-141 Initial Report for a release that occurred at our Loco Hills SWD 33 #004 on 12-05-2013 in Eddy County New Mexico. We plan to assess the spill area timely.

Thank you,

Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com

Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.