

Summary Report

COPY

Joel Martin
Nadel & Gussman Permian LLC
600 N. Marienfeld
Suite 508
Midland, TX 79701

Report Date: May 28, 2013

Work Order: 13052107



Project Location: Battery Remediation
Project Name: Valero State No. 1 Battery

Sample	Description	Matrix	Date Taken	Time Taken	Date Received
329881	E Side Aeration	soil	2013-05-20	09:00	2013-05-21
329882	W Side Aeration	soil	2013-05-20	09:20	2013-05-21
329883	Middle Aeration	soil	2013-05-20	09:30	2013-05-21
329884	Tank SW Area	soil	2013-05-20	10:15	2013-05-21
329885	Tank NW Area	soil	2013-05-20	10:40	2013-05-21

Sample - Field Code	BTX				TPH DRO - NEW	TPH GRO
	Benzene (mg/Kg)	Toluene (mg/Kg)	Ethylbenzene (mg/Kg)	Xylene (mg/Kg)	DRO (mg/Kg)	GRO (mg/Kg)
329881 - E Side Aeration	0.0226	0.223	0.0330	0.220	66.7 Qs	5.08 Qs
329882 - W Side Aeration	<0.0400 ¹	<0.0400	0.104	4.65	411 Qs	111 Qs
329883 - Middle Aeration	<0.0200	0.497	0.627	7.93	221 Qs	124 Qs
329884 - Tank SW Area	<4.00 ²	139	99.6	847	339 Qs	16800 Qs
329885 - Tank NW Area	<0.200 ³	11.74	<0.200	77.0	387 Qs	2530 Qs

¹Dilution due to excessive hydrocarbons.

²Dilution due to excessive hydrocarbons.

³Dilution due to excessive hydrocarbons.