


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

NJMN 1403048842

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Oxy Permian Ltd. 16696 Contact Chancey Summers
Address 1017 W. Stanolind Rd, Hobbs, NM 88240 Telephone No. (575) 397-8216
Facility Name State 27 #1 CTB Facility Type Gathering

Surface Owner (State OR Fed?) Mineral Owner API No. 30-015-29374

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	27	24S	29E					Eddy County, NM

Latitude N 32.19473° Longitude W 103.97987°

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 122 bbls	Volume Recovered 120 bbls
Source of Release 3 inch poly gas/water line from the facility to the main gas gathering system leaked	Date and Hour of Occurrence 01/06/2014	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher-NMOCD	
By Whom? Kathy Purvis	Date and Hour 01/09/2014	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A leak in the 3 inch poly gas/water line from the facility to the main gas gathering system caused 122 bbls of produced water to spill onto the ground. 120 bbls of produced water were recovered via vacuum truck and the line was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 5' x 100'. Remediation will be completed in accordance with a remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Printed Name: Chancey Summers

Title: HES Specialist

E-mail Address: Chancey.Summers@oxy.com

Date: 1-15-14 Phone: (575) 397-8216

OIL CONSERVATION DIVISION

Approved by Environmental Specialist

Signed By

Approval Date: JAN 29 2014

Expiration Date:

Conditions of Approval:

Remediation per UCD Rule &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NO LATER THAN:

Attached ☐

March 1, 2014

2RP-2172

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Thursday, January 16, 2014 11:30 AM
To: Bratcher, Mike, EMNRD
Cc: C J Summers; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com
Subject: Initial C-141, State 27 #1 CTB
Attachments: Initial C-141, State 27 #1 CTB.pdf

Attached is the initial C-141 for a leak that occurred at the State 27 #1 CTB on 01/06/2014 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis

BBC International, Inc.

1324 W. Marland

Hobbs, NM 88240

Phone: (575) 397-6388

Fax: (575) 397-0397

Email: kathy@bbcinternational.com

Bratcher, Mike, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Thursday, January 09, 2014 1:14 PM
To: Bratcher, Mike, EMNRD
Cc: C J Summers; Rachael_McPherson@oxy.com; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com
Subject: STATE 27 #1 CTB

This is to inform you that Oxy Permian Primary NM South had a release at the State 27 #1 CTB on January 6, 2014. Oxy released 122 bbls of produced water due to a leak in the 3 inch poly gas/water line from the facility to the main gas gathering system. 120 bbls of produced water were recovered via vacuum truck. The release is located in the Section 27, T24S, R29E of Eddy County, NM. BBC International will delineate the location at a later date and an initial C-141 will follow. Driving directions: From Carlsbad on Hwy 285 East, as road goes South, turn East on Duarte Rd for 1.3 miles, turn South on McDonald Rd, go 3 miles to CR788, turn North and go 1.5 miles, turn right on lease road and go 2.3 miles to cattleguard, turn right on lease road and go 0.8 mile to location.

Kathy Purvis

BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com