


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*1410539495* OPERATOR  Initial Report  Final Report

Name of Company: Cimarex Energy Company <i>162683</i>	Contact: Johnny Titsworth
Address: 600 N. Marienfield, Suite 600, Midland, TX 79701	Telephone No. (432)250-2059
Facility Name: Wersell Federal #2	Facility Type: SWD
Surface Owner: Federal	Mineral Owner:
API No. 30-015-24845	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	4	22S	27E	660	FNL	660	FWL	Eddy

Latitude: 32.42735 Longitude: -104.2009

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: 40	Volume Recovered: 0
Source of Release: 2" pipe	Date & Hour of Occurrence: 3/14/14 10:00	Date & Hour of Discovery: 3/14/14 10:30
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kim Barton	
By Whom? Jennifer Van Curen	Date and Hour: 3/14/14 10:30	
Was a Watercourse Reached? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Vibration caused the threads of the 2" pipe to crack at a 45 degree connection. Impacted soil will be assessed and remediated.		
Describe Area Affected and Cleanup Action Taken.* in the pasture: 45'x45', 120'x6', 75'x8'		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Johnny Titsworth	Approved by Environmental Specialist:	
Title: Environmental Compliance Coordinator	Approval Date: 4/15/14	Expiration Date: NA
E-mail Address: jtitsworth@cimarex.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4/10/14	Phone: (432)-250-2059	

\* Attach Additional Sheets, If Necessary

Remediation per OCD Rule & Guidelines. **SUBMIT REMEDIATION PROPOSAL NO LATER THAN:**  
5/15/14

*2RP-2260*

## Bratcher, Mike, EMNRD

---

**From:** Johnny Titsworth <jtitsworth@cimarex.com>  
**Sent:** Thursday, April 10, 2014 2:36 PM  
**To:** 'jvancure@blm.gov'; Bratcher, Mike, EMNRD  
**Cc:** Christine Alderman  
**Subject:** Wersell Fed #2  
**Attachments:** Wersell Fed 2.pdf

Mike/Jennifer,

We had a spill at the Wersell Fed #2. There were 40 barrels of PW lost with 0 recovered. Sorry that it took so long to get this in, we will get Talon out to assess the location and then start the remediation. Let me know if there is anything else you need.

**Johnny Titsworth**

***EHS - Environmental Compliance***

*600 N. Marienfeld St., Suite 600*

*Midland, TX 79701*

Mobile: 432-250-2059

Office: 432-620-1983

