

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*nHMP 1413238288*

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company: CIMAREX ENERGY <i>162683</i>	Contact: James Tinney	
Address : 600 N Marienfeld Ste 600, Midland TX 79701	Telephone No. (575) 706-0095	
Facility Name: Crow Flats 16 state 2H	Facility Type: Production Battery	
Surface Owner	Mineral Owner	API No. 30-015-35556

**LOCATION OF RELEASE**

Unit Letter M	Section 16	Township 016-S	Range 028-E	Feet from the 660	North/South Line south	Feet from the 330	East/West Line west	County ; Eddy
------------------	---------------	-------------------	----------------	----------------------	---------------------------	----------------------	------------------------	---------------

Latitude: 32.917130 Longitude: -104.188290

**NATURE OF RELEASE**

Type of Release: oil/produce water	Volume of Release: 15 oil/5 pw	Volume Recovered: 12 bbls total
Source of Release: hole in heater fire tube	Date and Hour of Occurrence: 5/4/2014 @ 0900 hrs	Date and Hour of Discovery: 5/4/2014 @ 0900 hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, 5/5/14 @ 0710 hrs, no answer left message	
By Whom? James Tinney	Date and Hour: 5/5/14 @ 0710 hrs	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**RECEIVED**

MAY 07 2014

**NMOCD ARTESIA**

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* hole in fire tube on heater, picked up standing oil and produce water. Release was in an unlined berm.

Describe Area Affected and Cleanup Action Taken.\*

Area affected 36' x 30' contained inside dirt berm (unlined). Called vac truck picked up standing oil and emptied heater.  
Work plan: repair equipment, pick up contaminated soil.

*Delineation Samples Required*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>James Tinney</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: James Tinney	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Production Foreman	Approval Date: <i>5/12/14</i>	Expiration Date: <i>NA</i>
E-mail Address: jtinney@cimarex.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN:</b> <i>6/12/14</i>	Attached <input type="checkbox"/>
Date: 05/05/2014	Phone: (575) 706-0095	

\* Attach Additional Sheets If Necessary

*2RP-2294*