

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Righthand Canyon 35-7	Facility Type	SWD

Surface Owner	Mineral Owner	API No.	30-015-34529
---------------	---------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	35	21S	24E					Eddy County, NM

Latitude N 32.43428° Longitude W 104.46379°

NATURE OF RELEASE

Type of Release	Produced water & Oil	Volume of Release	800 bbls water, 100 bbls oil	Volume Recovered	140 bbls
Source of Release	Gun Barrel Tank	Date and Hour of Occurrence		Date and Hour of Discovery	06/30/2011 @ 4:00 pm

Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher- NMOCD, Jim Amos- BLM
-----------------------------	---	------------------	-------------------------------------

By Whom?	Kelton Beard (Oxy)	Date and Hour	07/01/2011 @ 7:15 am
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED
FEB 14 2014
NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The collapse of a gun barrel tank caused 800 bbls of produced water and 100 bbls of oil to leak onto the ground. A vacuum truck picked up all free-standing fluids.

Describe Area Affected and Cleanup Action Taken.*
The area affected was on the location and into the pasture down the bottom of the slope North of the location. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 11/13/2012 and approved by James Amos of the BLM via email on 12/17/2012.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Christopher Jones	Approved by District Supervisor:	
Title:	HES Specialist	Approval Date:	5/16/14
E-mail Address:	Christopher.Jones@oxy.com	Expiration Date:	NA
Date:	2/12/14	Conditions of Approval:	Final
Phone:	(575) 628-4121	Attached	<input type="checkbox"/>

* Attach Additional Sheets If Necessary

2 RP-828

LINK 1