

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

MAR 04 2014

RECEIVED

Form C-141
Revised August 8, 2011

Submit Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: ConocoPhillips	Contact: Jose A Zepeda
Address: 1410 N West County Road	Telephone No. 575-391-3165
Facility Name: Harry Leonard Station 6	Facility Type: Battery

Surface Owner: STATE JAL 03/04/14	Mineral Owner: N/A	API No. 30-025-04759 JAL 03/04/14
---	---------------------------	---

LOCATION OF RELEASE

Unit Letter K	Section 22	Township 21	Range 36	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy LEA JAL 03/04/14
-------------------------	----------------------	-----------------------	--------------------	---------------	------------------	---------------	----------------	---

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: OIL&PDW	Volume of Release: 94.5	Volume Recovered: 23
Source of Release: Tank	Date and Hour of Occurrence 03/03/14 10:00am	Date and Hour of Discovery Same
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leking	
By Whom? Jose A Zepeda	Date and Hour: 03/03/14 13:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A

DTW = 157'

Describe Cause of Problem and Remedial Action Taken.*

On 3/03/14 @ ~1000 am @ the Harry Leonard Station 6 Battery, there was an accidental release of ~72.5 bbls of Oil & 22 bbls of PDW. COPC MSO was doing daily routine checks, pulled up to the Harry Leonard Station 6 Battery and observed PDW & Oil behind the west tank. COPC MSO noticed it was coming from the 4" Balon ball valve that had come apart, threads were broke and ball was sitting on the ground. COPC MSO notified Forman, HSE and contacted a vacuum truck. Vacuum truck recovered ~ 23 bbls of oil. A work order will be generated for cleanup and repairs. The spill site will be remediated in accordance with COPC and NMOCD guidelines. An Investigation into the cause of the incident is ongoing.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: JOSE A ZEPEDA		OIL CONSERVATION DIVISION Geoffrey Leking Approved by Environmental Specialist Environmental Specialist	
Printed Name: Jose A Zepeda		Approval Date: 03/04/14 Expiration Date: 05/05/14	
Title: LEAD HSE		Conditions of Approval: SUBMIT FINAL C-141 BY 05/05/14	
E-mail Address: Jose. A. Zepeda@conocophillips.com		Attached <input type="checkbox"/>	
Date: 03/04/14 Phone: 575-391-3158		IRP-06-14-3077	

* Attach Additional Sheets If Necessary

JUN 10 2014