

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD

JAN 03 2013

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RELEASE Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

| | | | |
|-----------------|------------------------------|---------------|-----------------|
| Name of Company | Apache Corporation | Contact | Natalie Gladden |
| Address | PO Box 1849, Eunice NM 88231 | Telephone No. | 575-390-4186 |
| Facility Name | Seven Rivers Queen Unit #421 | Facility Type | Injection Well |
| Surface Owner | Deck Estate | Mineral Owner | State |
| | | API No. | 30-025-09022 |

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| E | 25 | 22S | 36E | 1980 | FNL | 660 | FWL | Lea |

Latitude _____ Longitude _____

NATURE OF RELEASE

| | | | | | |
|-----------------------------|---|---|-----------------|----------------------------|------|
| Type of Release | Produced Water | Volume of Release | 400 | Volume Recovered | 15 |
| Source of Release | Injection line | Date and Hour of Occurrence | 09/27/12 | Date and Hour of Discovery | Same |
| Was Immediate Notice Given? | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? | Geoffrey Leking | | |
| By Whom? | Natalie Gladden | Date and Hour | 09/27/12 | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | | | |

If a Watercourse was Impacted, Describe Fully.*

DTW = 220'



Describe Cause of Problem and Remedial Action Taken.*

Injection line leak due to line rupture released fluid down right-of-way. An attempt to recover the released fluids, which resulting in 15 of the 400bbls to be recovered. Saturation levels caused the vacuum trucks to get stuck, therefore all recovery efforts were stopped. The line was excavated and replaced.

Describe Area Affected and Cleanup Action Taken.*

All NMOCD guidelines will be followed to closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|--|---|-----------------------------------|
| Signature:  | OIL CONSERVATION DIVISION | |
| Printed Name: Natalie Gladden | Approved by Environmental Specialist:  Environmental Specialist | |
| Title: Sr. Environmental Tech | Approval Date: 01/03/13 | Expiration Date: 03/04/13 |
| E-mail Address: natalie.gladden@apachecorp.com | Conditions of Approval: SUBMIT FINAL C-141 BY 03/04/13 | Attached <input type="checkbox"/> |
| Date: 10/01/12 Phone: 575-390-4186 | HRP-06-14-3087 | |

* Attach Additional Sheets If Necessary

JUN 17 2014

NSAD1416734222