

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report

☒ Final Report

Name of Company	COG OPERATING LLC	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	SRO 17 State Com	Facility Type	Tank Battery

Surface Owner	State	Mineral Owner		Lease No. (API#)	30-015-38257
---------------	-------	---------------	--	------------------	--------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	09	26S	28E					Eddy

Latitude 32.06168

Longitude 104.09991

### NATURE OF RELEASE

Type of Release Produced water	Volume of Release 15bbls	Volume Recovered 14bbls
Source of Release Poly line Y connection	Date and Hour of Occurrence 01-21-2014	Date and Hour of Discovery 01-21-2014 1:00pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

**JUN 06 2014**

Describe Cause of Problem and Remedial Action Taken.\*

The connection on the Y failed due to moving the line a week earlier.

**RECEIVED**

Describe Area Affected and Cleanup Action Taken.\*

Initially 15bbls of produced water were released. We were able to recover 14bbls of produced water with a vacuum truck. All free fluids have been recovered. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Michelle Mullins</i>		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Michelle Mullins		Approved by District Supervisor: <i>[Signature]</i>	
Title: Environmental Coordinator		Approval Date: <i>6/11/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: mmullins@concho.com		Conditions of Approval: <i>Final</i>	
Date: 06-06 -2014 Phone: 432-934-1052		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

*2RP-2183*