

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD

OCT 14 2013

RECEIVED

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Apache Corporation	Contact Bruce Baker
Address 8 Ellison Lane Eunice, NM 88231	Telephone No. (432) 631-6982
Facility Name NEDU Central Tank Battery (nearest well # 421)	Facility Type Battery

Surface Owner WFM Ranch Ltd. Et al	Mineral Owner	API No. 30-025-37028-37026
------------------------------------	---------------	----------------------------

LOCATION OF RELEASE

Unit Letter A	Section 10	Township 21S	Range 37E	Feet from the 1310'	North/South Line FNL	Feet from the 330'	East/West Line FEL	County Lea
---------------	------------	--------------	-----------	---------------------	----------------------	--------------------	--------------------	------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 25 BBLS	Volume Recovered 20 BBLS
Source of Release injection line	Date and Hour of Occurrence	Date and Hour of Discovery 10-6-13 at 8:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mr. Leking	
By Whom? Bruce Baker	Date and Hour 10/7/13 at 9:16 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

DTW = 25'

Describe Cause of Problem and Remedial Action Taken.*

The line was shut in and a vacuum truck was dispatched to pick up fluid.

Describe Area Affected and Cleanup Action Taken.*

A total of 14,290 square feet of area affect with 10,229 square feet pasture. Once line is repaired the site will be delineated.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Bruce Baker	OIL CONSERVATION DIVISION <i>Larry Baker</i> Approved by Environmental Specialist Environmental Specialist	
Printed Name: Bruce Baker		
Title: Environmental Technician	Approval Date: 10/15/13	Expiration Date: 12/16/13
E-mail Address: larry.baker@apachecorp.com	Conditions of Approval: SUBMIT FINAL C-141 BY 12/16/13	Attached <input type="checkbox"/>
Date: 10-14-13 Phone: (432) 631-6982	IRP-11-13-2987	

* Attach Additional Sheets If Necessary

MSAD 1417754308

R