District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD State of New Mexico JUN 27 2014 **Oil Conservation Division**

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141 Revised August 8, 2011

1220 South St. Francis Dr. RECEIVED Santa Fe, NM 87505

Release Notification and Corrective Action

	OPERATOR	🛛 Initial Report	Final Report
Name of Company Devon Energy	Contact Kenny Kidd		
Address PO Box 250 Artesia, NM 88211	Telephone No. 575- 513-8545		
Facility Name Red Bull 31 State 1	Facility Type Gas		
Surface Owner: Limestone Livestock	Mineral Owner: State of New Mexico	API No. 30-025-3679	8

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	31	235	35E	1300	SOUTH	2610	West	LEA

Latitude: _32.15265 __ Longitude: _103.24244 __

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release 12bbls	Volume Recovered 2bbis			
Source of Release: Tank valves left open	Date and Hour of Occurrence	Date and Hour of Discovery			
	June 17, 2014 9:30 AM	June 17, 2014 9:30 AM			
Was Immediate Notice Given?	If YES, To Whom?				
🛛 Yes 🔲 No 🗌 Not Required		n/Kenny Kidd-Foreman/Amancio Cruz-			
	EHS/Roy White-Sr Production Fe	oreman/Maxey Brown-OCD/Jeffery			
	Robertson-BLM				
By Whom? Terry Bryan	Date and Hour: June 17, 2014 9:30				
Was a Watercourse Reached?	If YES, Volume Impacting the Wat	ercourse.			
🗌 Yes 🖾 No					
If a Watercourse was Impacted, Describe Fully.*					
in a watercourse was impacted, Describe Funy.	Vepta	To g40-~SO'-75'			
Describe Cause of Problem and Remedial Action Taken.*					
At the Red Bull 31-1, a truck driver from Basic picked up a load of p	roduced water and after loading he	did not close the valve on the water tank			
and the valve at the end of the load line causing 12 barrels of produce					
valves and notified the Assistant Foreman and Basic was called for va					
		_			
Describe Area Affected and Cleanup Action Taken.*					
The area affected within the facility was 81 feet wide by 78 feet long.	Talon LPE was contacted to perform	m the site assessment and soil sampling			
activities.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and					
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger					
public health or the environment. The acceptance of a C-141 report by the					
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health					
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other					
federal, state, or local laws and/or regulations.					
Signature Of C	<u>OIL CONSERV</u>	ATION DIVISION			
Signature: Chammy Ingram					
Deleted M. Chemery Ingree					
Printed Name: Shammy Ingram	Approvee by Environmental Specialis	51:			
	10. (1231-				
Title: Field Admin Support	Approval Date: 6/27/14	Expiration Date: 8-29-19			
E-mail Address: Shammy. Ingram@dvn.com	ه وسده Conditions of Approval: Sive Samp la	Attached			
	relinvagel remediate the and				
Date: June 26, 2014 Phone: 575-748-0174	Conditions of Approval: Site Samp la Relinvater remodiate the area Nm OCD guides . Subart Fi by 8-29-14	RSper 6-14-3120 Int cia 03rid 6137 Ato 14			
Attach Additional Sheets If Necessary	gures Subart F	Ind city ogrid 6137			
	by 8-29-14	Ato ly			

JUN 3 0 2014

p 1014