

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

HOBBS OCD

JUN 27 2014

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: ConocoPhillips	Contact: Spencer Cluff
Address: 29 Vacuum Complex Lane	Telephone No. 575-391-3143
Facility Name: EVGSAU Well 3308-006	Facility Type: Oil Well

Surface Owner: NMOCD	Mineral Owner NMOCD	API No. 3002532062
-----------------------------	----------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	33	17S	35E	900	North	1860	West	LEA

Latitude **32.7962127697422** Longitude - **103.465196780244**


NATURE OF RELEASE

Type of Release: Spill	Volume of Release: 7.2 BBLs	Volume Recovered: 0 BBLs
Source of Release: Stuffing Box	Date and Hour of Occurrence 6/17/2014 2:00 p.m.	Date and Hour of Discovery 6/17/2014 2:00 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leking	
By Whom? Spencer Cluff	Date and Hour: 06/27/2014 4:15 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

Describe Cause of Problem and Remedial Action Taken.* On Tuesday June 17, 2014 @ 1400 hrs. MST @ the EVGSAU 3308-006, an accidental discharge of 7.27 BO occurred. MSO received a call from another MSO that the O-ring and rams failed in the stuffing box, causing a release. The spill area was 23 ft. X 27 ft. X 0.5 inches deep, all on the caliche pad. MSO turned off well and closed tubing and casing to isolate well. MSO submitted a work order to repair the stuffing box. The spill area will be remediated according to NMOCD requirements.

Describe Area Affected and Cleanup Action Taken.* The spill area was 23 ft. X 27 ft. X 0.5 inches deep, all on the caliche pad. The spill area will be remediated according to NMOCD requirements.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

		OIL CONSERVATION DIVISION	
Signature: <i>Spencer A. Cluff</i>		 Approved by Environmental Specialist:	
Printed Name: Spencer A. Cluff			
Title: LEAD HSE	Approval Date: 6-30-14	Expiration Date: 9-1-14	
E-mail Address: spencer.a.cluff@conocophillips.com	Conditions of Approval: <i>Site Samples</i> <i>reporals</i> <i>Deliverte & Remediate Site as per</i> <i>NMOCD Guides. Submit form</i>		Attached <input type="checkbox"/>
Date: 06/27/2014	Phone: 575-391-3143	6-14-3127	

* Attach Additional Sheets If Necessary

C-141 by 9-1-14.

09174 217817
8701418 156981

JUL 01 2014