1625 N. French Dr., Hobbs, NM 88240	tte of New Mexico HOBBS OCD Form C-141 herals and Natural Resources Revised August 8, 2011
811 S. First St., Artesia, NM 88210	nerals and Natural Resources Revised August 8, 2011
1000 Rio Brazos Road, Aztec, NM 8/410	onservation Division South St. Francis Dr.
1200 G. G. Francis Dr. Grade Fr. NIM 97505	South St. Francis Dr. nta Fe, NM 87505 <b>RECEIVED</b>
	ation and Corrective Action
	<b>OPERATOR</b>
Name of Company: ConocoPhillips	Contact: Jose A Zepeda
Address: 1410 N West County Road Facility Name: SEMU Permian Battery	Telephone No. 575-391-3165 Facility Type: Battery
Surface Owner: Federal Lease Mineral Ow	2002502910
	TION OF RELEASE 30 005 0 78 2 0
Unit LetterSectionTownshipRangeFeet from theK1920S38E	North/South Line Feet from the East/West Line County Lea
Latitude	Longitude
NATU	URE OF RELEASE
Type of Release: OIL	Volume of Release: 5.5 BBLS Volume Recovered: 5.0 BBLS
Source of Release: Site Glass on Heater Treater	Date and Hour of OccurrenceDate and Hour of Discovery06/16/2014 ~0700amSAME
Was Immediate Notice Given?	If YES, To Whom?
Not sure if it was state Yes No Not Requ	
By Whom? Jose A Zepeda Was a Watercourse Reached?	Date and Hour: 06/16/2014 ~1100 am Email   If YES, Volume Impacting the Watercourse.
🗌 Yes 🖾 No	Depth to gH, 0 ~ 75-100
If a Watercourse was Impacted, Describe Fully.*	
~ 5.5 bbl. of Oil - RR2. On June 16, 2014 @ ~0700 am @ the SEM doing daily routine checks, pulled up to the SEMU Permian Battery COPC MSO noticed a broken site glass on Heater Treater. COPC M	- Agency Reportable - MCBU - Permian - SENM - Hobbs - SEMU Permian Battery + AU Permian Battery, there was an accidental release of ~5.5 bbl. of Oil. COPC MSO was y and observed oil on the ground at location. Upon checking area and shutting in well MSO notified Forman, HSE and contacted a vacuum truck. Vacuum truck recovered ~ pairs. The spill site will be remediated in accordance with COPC and NMOCD ng.
Describe Area Affected and Cleanup Action Taken.*	ete to the best of my knowledge and understand that pursuant to NMOCD rules and
regulations all operators are required to report and/or file certain rel public health or the environment. The acceptance of a C-141 report should their operations have failed to adequately investigate and rem	elease notifications and perform corrective actions for releases which may endanger rt by the NMOCD marked as "Final Report" does not relieve the operator of liability emediate contamination that pose a threat to ground water, surface water, human health report does not relieve the operator of responsibility for compliance with any other
	OIL CONSERVATION DIVISION
Signature: JOSE A 3EPEDA	
Printed Name: Jose A Zepeda	Approved by Environmental Specialist:
Title: LEAD HSE	Approval Date: $7-3$ Expiration Date: $9-6-19$
E-mail Address: Jose. A, Zepeda@conocophillips.com	
Date: 06/17/2014 Phone: 575-391-315	58 Submit fiel (-141 by 9=5-14 7-14-3139
Attach Additional Sheets If Necessary	0grid \$17817
	JUL 09 2014 NTO 14 1897 356 PTO 14 18431627

·