District I State of	of New Mexico	HOBBS OCD		
1625 N. French Dr., Hobbs, NM 88240	ls and Natural Resources		Form C-141 Revised August 8, 2011	
811 S. First St., Artesia, NM 88210	ervation Division	MAY 1 5 2014 opy	to appropriate District Office in	
1000 Rio Brazos Road Aztec, NM 87410	ith St. Francis Dr.	ac	cordance with 19.15.29 NMAC.	
1000 G G D	Santa Fe, NM 87505 <b>RECEIVED</b>			
Release Notification and Corrective Action				
<b>OPERATOR</b> Initial Report Final Report				
Name of Company: ConocoPhillips	Contact: Spencer Cluff			
Address: 29 Vacuum Complex Lane	Telephone No. 575-391-3143			
Facility Name: ABO 13-10	Facility Type: Well			
Surface Owner: NMOCD Mineral Owne	ner: NMOCD API No. 30-025-03070			
LOCATION OF RELEASE				
Unit LetterSectionTownshipRangeFeet from theNorJ0518S35E1980Sou	th/South LineFeet from thth2310	e East/West Line East	County LEA	
Latitude 32.8057498009579 Longitude 103.446081589692	E OF RELEASE			
Type of Release: Spill	Volume of Release: 21.0	5 BBLS Volume F	Recovered: 3 BBLS	
Source of Release: Flow Line	Date and Hour of Occurr	ence Date and	Hour of Discovery	
Was Immediate Notice Given?	5/14/2014 7:00 am If YES, To Whom?	5/14/14	2:45 pm	
🗌 Yes 🗌 No 🛛 Not Require				
By Whom? Spencer Cluff Was a Watercourse Reached?	Date and Hour: 05/15/2014 10:15 am			
Was a watercourse Reached?	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*		depth	+0 9 H10 50'-75'	
	,			
Describe Cause of Problem and Remedial Action Taken.*				
May 13, 2014 at 1100, a discharge occurred on the ABO 13-10 flow line. Pipeline pilot discovered the leak while flying the area. Well was				
shut down within a few minutes after discovery and flow line was isolated at the well and header. Total volume of the spill was 21.05 bbls, with 6 BO and 15.05 BPW. Vacuum truck recovered approximately 1.5 BO and 1.5 BPW. Affected area was 45 ft. X 36 ft. X 12 inches deep				
in soil of pasture. MSO notified Operation Supervisor and the HSE. G.P.S. of leak location is 32°46'34"N 103°28'33"W.				
Describe Area Affected and Cleanup Action Taken.*				
Affected area was 45 ft. X 36 ft. X 12 inches deep in soil of pasture.				
I hereby certify that the information given above is true and complete to				
regulations all operators are required to report and/or file certain release public health or the environment. The acceptance of a C-141 report by	the NMOCD marked as "Fina	l Report" does not reli	ieve the operator of liability	
should their operations have failed to adequately investigate and remed or the environment. In addition, NMOCD acceptance of a C-141 repor				
federal, state, or local laws and/or regulations.			-	
	<u>OIL CC</u>	NSERVATION	DIVISION	
Signature: Spencer A. Cluff				
Printed Name: Spencer Cluff	Approved by Environmental Specialist:			
Title: LEAD HSE	Approval Date: <b>7-7-</b> /	• Expiration	Date: 9-10-14	
E-mail Address: <b>spencer.a.cluff@conocophillips.com</b>	Conditions of Approval:			
		urrode	Attached	
	Site Samples - eq. Delini tree rome. Ber NMOCO guide	date groz as		
Date: 05/15/2014 Phone:575-391-3143	MER NMOCO guides	s. Submitfield	7-14-3145	
Attach Additional Sheets If Necessary	(-141 by 9-10-14		ogrid 217817	
	ai I	UL 0 9 2014	NTO 1418 852147	
			p to 1418 852434	