

HOBBS OCD

MAY 19 2014

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Mewbourne Oil Company	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: QPQASU #10	Facility Type: Producing Oil Well
Surface Owner: BLM	Mineral Owner: BLM
API No. 30-025-28908	

LOCATION OF RELEASE

Unit Letter O	Section 21	Township 18S	Range 32E	Feet from the 660'	North/South Line South	Feet from the 1650'	East/West Line East	County Lca
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	---------------

Latitude 32.726192 Longitude -103.761283

NATURE OF RELEASE

Type of Release: Oil/ Produced Water	Volume of Release: Unknown	Volume Recovered: 500 bbls (Oil)/ 0 bbls (PW)
Source of Release: Flow Line	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: 5-15-14 1:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoff Leking, Jim Amos	
By Whom? Zack Thomas	Date and Hour: 5-15-14 5:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Depth to H₂O 7100'

Describe Cause of Problem and Remedial Action Taken.*

Failure of a poly flow line resulted in the release of an unknown volume of a mixture of crude oil and produced water. Following the discovery of the release, the well was shut in and the flow line was repaired. A vacuum truck was used to recover approximately 500 bbls of free standing fluid.

Describe Area Affected and Cleanup Action Taken.*

The release impacted an area of pasture land measuring approximately 5,500 sq. ft. Saturated soil will be scrapped up and placed on a poly liner pending BLM Arch and One-Call clearance. The release occurred adjacent to two historical releases which will be remediated in the same manner. Final remediation will be conducted in accordance with the NMOCD's Guidelines for Remediation of Spills, Leaks and Releases.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Z. Thomas</i>	OIL CONSERVATION DIVISION	
Printed Name: Zack Thomas	Approved by Environmental Specialist:	
Title: Environmental Rep.	Approval Date: 7-7-14	Expiration Date: 9-10-14
E-mail Address: zthomas@mewbourne.com	Conditions of Approval: Site Samples required. Delimited remediate area as per NMOCD guide. Submit final C-141 by 9-10-14	Attached <input type="checkbox"/> 7-14-3147
Date: 5-19-14	Phone: 575-602-2188	

* Attach Additional Sheets If Necessary

JUL 09 2014

5/19

03rid 14744
170 1418 855194
P+0 1418 855412