

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OCD

Form C-141  
Revised August 8, 2011

MAY 13 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company: Cimarex Energy Company	Contact: Johnny Titsworth
Address: 600 N. Marienfield, Suite 600, Midland, TX 79701	Telephone No. (432)250-2059
Facility Name: Triste Draw 30 Federal #1	Facility Type: Tank Battery

Surface Owner: Federal	Mineral Owner:	API No. 30-025-41174
------------------------	----------------	----------------------

**LOCATION OF RELEASE**

Unit Letter M	Section 30	Township 23S	Range 33E	Feet from the 330	North/South Line FSL	Feet from the 660	East/West Line FWL	County Lea
------------------	---------------	-----------------	--------------	----------------------	-------------------------	----------------------	-----------------------	---------------

Latitude: 32.26943 Longitude: -103.61759

**NATURE OF RELEASE**

Type of Release: oil	Volume of Release: 10	Volume Recovered: 7
Source of Release: LACT unit	Date & Hour of Occurrence: 5/5/14	Date & Hour of Discovery: 5/5/14 12:00
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jennifer Van Curen	
By Whom? Johnny Titsworth	Date and Hour: 5/6/14	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

GW = 425'

Describe Cause of Problem and Remedial Action Taken.\*

1/2" valve below the screen pot was left open filling up the LACT unit containment & ran onto location (60'x27').

Describe Area Affected and Cleanup Action Taken.\*

7 BBLS in containment & 3 BBLS on pad. Discussed spill with BLM (Jennifer Van Curen), and pad will be scraped and replaced with fresh caliche

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature:

Printed Name: Johnny Titsworth

Approved by Environmental Specialist:

Title: Environmental Compliance Coordinator

Approval Date: 7-8-14

Expiration Date: 9-11-14

E-mail Address: jtitsworth@cimarex.com

Conditions of Approval:

Site Supplies required.

Attached ☐

Date: 5/13/14

Phone: (432)-250-2059

7-14-3150

\* Attach Additional Sheets If Necessary

Delimited remediate area as per NMOCD guidelines. Submit final C-141 by 9-11-14

09/14 215099  
N701418 941914  
P701418 942122

JUL 09 2014