

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
120 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD

JUL 08 2014

RECEIVED

State of New Mexico

Energy Minerals and Natural Resources

Oil Conservation Division

1220 South St. Francis Dr.

Santa Fe, NM 87505

HOBBS OCD

JUL 08 2014

RECEIVED

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report

☒ Final Report

Name of Company	COG OPERATING LLC	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Stratocone 32 State #001	Facility Type	Tank Battery

Surface Owner	State	Mineral Owner		Lease No. (API#)	30-025-40617
---------------	-------	---------------	--	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	32	20S	35E					Lea

Latitude 32.52867

Longitude 103.48685

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 60bbbs	Volume Recovered 55bbbs
Source of Release Lightning strike to water tank	Date and Hour of Occurrence 06-20-2014	Date and Hour of Discovery 06-20-2014 08:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomas Oberding & Geoffrey Leking - NMOCD	
By Whom? Michelle Mullins	Date and Hour 06-20-2014 6:44pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A lightning strike struck the water tank causing the bottom to separate from the sides. We will replace the water tank with a new one.

Describe Area Affected and Cleanup Action Taken.*

Initially 60bbbs of produced water were released. We were able to recover 55bbbs of produced water with a vacuum truck. The spill was contained inside the lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned and we has replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Grubbs Jr.</i>	OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.	Approved by District Supervisor: <i>Environmental Specialist</i>	
Title: Senior Environmental Coordinator	Approval Date: 7-8-14	Expiration Date: _____
E-mail Address: rgrubbs@concho.com	Conditions of Approval: _____	
Date: 06-20-2014 Phone: 432-661-6601	Attached <input type="checkbox"/> 7-14-3152	

Attach Additional Sheets If Necessary

JUL 09 2014

67014 229137
1701418
p 701418 495337