

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**HOBBS OCD**

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

**APR 01 2014**

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**RECEIVED**

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company XTO Energy	Contact John Robinson
Address PO Box 700 Eunice N.M.: 88231	Telephone No. 575-441-5199
Facility Name EMSU 652	Facility Type Production Well

Surface Owner	Mineral Owner State	API No. 30-025-34140
---------------	---------------------	----------------------

### LOCATION OF RELEASE

Unit Letter O	Section 5	Township 21-S	Range 36-E	Feet from the 84'	North/South Line SOUTH	Feet from the 1445'	East/West Line EAST	County Lea
------------------	--------------	------------------	---------------	----------------------	---------------------------	------------------------	------------------------	---------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

### NATURE OF RELEASE

Type of Release produced wtr and oil	Volume of Release 31 bbls	Volume Recovered 30 bbls
Source of Release Flow Line	Date and Hour of Occurrence 3-31-14 10:30 am	Date and Hour of Discovery 3-31-14 10:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Called Jeff and talked to him at 2:20 pm	
By Whom? John Robinson	Date and Hour 3-31-14 2:20pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Back Hoe hit flowline while digging. EPI will clean up to state standards.

Describe Area Affected and Cleanup Action Taken.\*

Pasture. Sucked up all the fluid we could with truck and will start cleanup as soon as one call is up.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: John Robinson	Approved by Environmental Specialist: 	
Title: Maintenance Foreman	Approval Date: 7-9-14	Expiration Date: 9-2-14
E-mail Address: john_robinson@xtoenergy.com	Conditions of Approval: Site Samples required Deliniate & remediate to NMOCD guides. Submit from C-141 by 9-12-14	Attached <input type="checkbox"/> 7-14-3160
Date: 3-31-14 Phone: 575-441-5199		

\* Attach Additional Sheets If Necessary

**JUL 09 2014**

05-11 5380  
NTD 1419  
PTO 1419 0355