

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1420950822

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Vanguard Permian	<i>258350</i>	Contact Mike Jones
Address 5847 San Felipe, Ste. 3000 Houtston, TX 77057		Telephone No. 575-390-4611
Facility Name Onsurez #1		Facility Type Battery

Surface Owner Antonio and Gloria Onsurez	Mineral Owner	API No. 30-015-23592
--	---------------	----------------------

LOCATION OF RELEASE

Unit Letter C	Section 11	Township 23s	Range 28 e	Feet from the 672	North/South Line FNL	Feet from the 1773	East/West Line FWL	County EDDY
------------------	---------------	-----------------	---------------	----------------------	-------------------------	-----------------------	-----------------------	----------------

Latitude 32.325488 **Longitude** -104.060743

NATURE OF RELEASE

Type of Release Oil and Produced Water	Volume of Release 10 BBLS	Volume Recovered 5 BBLS
Source of Release Oil and Gas separator Pop off	Date and Hour of Occurrence	Date and Hour of Discovery 6-13-14/9AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

NM OIL CONSERVATION
ARTESIA DISTRICT
JUL 25 2014

Describe Cause of Problem and Remedial Action Taken.*

Pop off on separator, releases and blow mist of oil and water in pasture. Pop off was replaced and piped to water tank.

RECEIVED

Describe Area Affected and Cleanup Action Taken.*

A total of 8,871 square feet of lease pad a pasture land was affected. The site will be assessed and a Corrective Action plan will be submitted to NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Mike Jones</i>		OIL CONSERVATION DIVISION	
Printed Name: Mike Jones		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Production Foreman		Approval Date: <i>7/28/14</i>	Expiration Date: <i>NA</i>
E-mail Address: <i>mjones@vnrllc.com</i>		Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	
Date: _____ Phone: 575-390-4611		Attached <input type="checkbox"/> <i>RP2-2397</i>	

* Attach Additional Sheets If Necessary

8/28/14