

AUG 28 2014

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submitted to the appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Devon Energy	Contact Kenny Kidd
Address PO Box 250 Artesia, NM 88211	Telephone No. 575-513-8545
Facility Name Caswell 23 1H	Facility Type Oil

Surface Owner	Mineral Owner	API No. 30-025-40708 1RP-05-14-3046
---------------	---------------	--

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	23	17S	32E	335	North	260	EAST	LEA

Latitude: 32.8263865°N Longitude: -103.7293355°W

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 15bbls	Volume Recovered 10bbls
Source of Release Jet pump malfunction	Date and Hour of Occurrence 5/12/14 9:45 am	Date and Hour of Discovery 5/12/14 9:45 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Garry Michael Assistant Foreman/Kenny Kidd-Foreman/Scott Pae-EHS/Jerry Mathews-Superintendent/OCD-voicemall/BLM-Jeff L. Robertson	
By Whom? Jeff Ables	Date and Hour 5/12/14 9:45 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Packing blown from jet pump resulting in approx. 15bbls produced water spill. The BLM and the OCD was notified on May 13, 2014 at 7:31 am and 7:49 am respectively. The size of the spill area was about 150 feet by 60 feet. Approximately 10bbls were recovered from the ground.

Describe Area Affected and Cleanup Action Taken.* **The impacted area in the vicinity of S-1, S-2, S-3, S-5, test pit location TP-1 and TP-2 was excavated to a depth of 1-foot deep. The impacted area in the vicinity of S-4 and TP-3 was excavated to a depth of 0.5-foot deep. The impacted area in the vicinity of TP-4 was excavated to a depth of 2-feet deep in accordance with NMOCD and BLM approved work plan. All the contaminated soil was transported to Lea Land, LLC. The excavated areas were then backfilled with new caliche; machine compacted and contoured to match the surrounding location. No further action is required.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sandra D. Farley</i>	OIL CONSERVATION DIVISION	
Printed Name: SANDRA D. FARLEY	Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: 8-28-14	Expiration Date: _____
E-mail Address: Sandra.Farley@dvn.com	Conditions of Approval:	Attached <input type="checkbox"/> 1RP-3046
Date: August 27, 2014	Phone: 575-746-5587	

* Attach Additional Sheets If Necessary

AUG 28 2014