

AUG 27 2014

District I
1635 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED

State of New Mexico
Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 5, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Oxy USA Inc.	Contact: Austin Trammell
Address: 1017 W Stanolind Road	Telephone No: 575-499-4919
Facility Name: Cotton Draw Unit 10	Facility Type: Well location
Surface Owner: BLM	Mineral Owner: API No: 30-025-08195

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	16	25S	32E	660	N	660	E	Lea

Latitude: 32.13683° Longitude: -103.67362°

NATURE OF RELEASE


Type of Release: Produced Water	Volume of Release: 35BBL	Volume Recovered: 30BBL
Source of Release: 2" steel production line due to internal corrosion	Date and Hour of Occurrence: 04/01/2014 @ 2:00 PM	Date and Hour of Discovery:
Was Immediate Notice Given? ☒ Yes ☐ No ☐ Not Required	If YES, To Whom? Geoffrey Laking NMOCD, Jennifer Van Curen BLM	
By Whom? Austin Trammell	Date and Hour 04/02/2014 @ 02:37 PM	
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse:	

If a Watercourse was Impacted, Describe Fully:

Describe Cause of Problem and Remedial Action Taken:
Internal corrosion on a 2" steel production flow line cause 35 bbls of produced water to leak onto the ground; 30 bbls of fluid was recovered and well was shut in.

Describe Area Affected and Cleanup Action Taken:
The affected area is approximately 18'x46'. Remediation will be completed in accordance with an approved remediation plan from the NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Austin Trammell	Approved by Environmental Specialist:	
Title: HES Specialist	Approval Date: 8-27-14	Expiration Date: 10-28-14
E-mail Address: Austin_trammell@oxy.com	Conditions of Approval: Site Specific report	Attached ☐ IRP: 3278
Date: 04/14/2014 Phone: 575-499-4919		

* Attach Additional Sheets If Necessary

Delante & remediate area
in per NMOCD guidelines
submit final C-141 by 10-28-14
Ogrod 16696
N701424 026931
P701424 027067

AUG 28 2014