

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OCD

SEP 03 2014

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Apache Corporation	Contact Natalie Gladden
Address PO Box 1849, Eunice NM	Telephone No. 575-390-4186
Facility Name WBDU #106	Facility Type Production Well
Surface Owner Deck	Mineral Owner State of NM
API No. 30-025-39407	

LOCATION OF RELEASE


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	8	21S	37E	2310	FSL	2310	FEL	Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release Oil	Volume of Release 25	Volume Recovered 20
Source of Release BOP Failure	Date and Hour of Occurrence 5/8/11	Date and Hour of Discovery 5/8/11
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Leking	
By Whom? Natalie Gladden	Date and Hour 5/9/11 at 113pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* BOP failed to hold, releasing fluid. Fluid was recovered and one-call was made.		
Describe Area Affected and Cleanup Action Taken.* NMOCD guidelines will be followed to closure.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Natalie Gladden	Approved by Environmental Specialist:	
Title: EHS-Environmental Tech	Approval Date: 9-3-14	Expiration Date: 11-3-19
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval: SITE 9/3/14 report	Attached <input type="checkbox"/> IRP-3305
Date: 5/12/11 Phone: 575-390-4186		

\* Attach Additional Sheets If Necessary

Revised 8/11/11 as per  
NMOCD guide. Subrio  
Final C-141 by 11-3-14

Ogriid 873  
H701424654156  
P7014246541263

SEP 05 2014