

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION  
ARTESIA DISTRICT

SEP 11 2014

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

*NABI425529738*

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: <b>OXY USA Limited Partnership</b> <i>1104910</i>	Contact: <b>Chris Jones</b>	
Address: <b>102 S. Main St. Carlsbad, NM 88220</b>	Telephone No.: <b>575-628-4121</b>	
Facility Name: <b>Conoco 10 State #2H</b>	Facility Type: <b>Battery</b>	
Surface Owner: <b>State</b>	Mineral Owner:	API No.: <b>30-015-39112</b>

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<b>M</b>	<b>10</b>	<b>19S</b>	<b>29E</b>	<b>580'</b>	<b>South</b>	<b>660'</b>	<b>West</b>	<b>Eddy</b>

Latitude **32.669563 N** Longitude **-104.0691133 W**

NATURE OF RELEASE

Type of Release: <b>Produced Water</b>	Volume of Release: <b>70 bbls</b>	Volume Recovered: <b>70 bbls</b>
Source of Release: <b>Leak in Steel Tank</b>	Date and Hour of Occurrence <b>9/2/14</b>	Date and Hour of Discovery <b>9/2/14</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Email: <b>Mike Bratcher OCD</b>	
By Whom? <b>Chris Jones</b>	Date and Hour: <b>9/3/2014 6:58 am</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* <b>A steel water tank was found to be leaking due to internal corrosion resulting in a release of 70 barrels of produced water inside the lined containment of the facility. The well was shut in, the tank was repaired and put back into service. A vac truck was immediately called to the location and recovered 70 barrels of fluids.</b>		
Describe Area Affected and Cleanup Action Taken.* <b>No further actions are required.</b>		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <b>Chris Jones</b>		OIL CONSERVATION DIVISION
Printed Name: <b>Chris Jones</b>		Approved by Environmental Specialist <i>[Signature]</i>
Title: <b>HES Specialist</b>	Approval Date: <b>9/12/14</b>	Expiration Date: <b>N/A</b>
E-mail Address: <b>Christopher.Jones@oxy.com</b>	Conditions of Approval: <b>FINAL</b>	Attached <input type="checkbox"/>
Date: <b>9/3/2014</b>	Phone: <b>575-628-4121</b>	

\* Attach Additional Sheets If Necessary

*2RP 2482*

## Bratcher, Mike, EMNRD

---

**From:** Kimberly M. Wilson <kwilson@talonlpe.com>  
**Sent:** Thursday, September 11, 2014 11:10 AM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD  
**Cc:** Christopher\_Jones@oxy.com; David Adkins  
**Subject:** Conoco 10 State #2  
**Attachments:** Conoco 10 State #2H initial final C-141.pdf

Mike and Heather,

Attached please find the initial and final C-141 for the above referenced release. If I have already sent this I'm sorry. I'm having trouble with my emails and can't find the sent confirmation.

Thank you.

Respectfully submitted,

***Kimberly M. Wilson***

Project Manager  
Talon/LPE  
408 West Texas Avenue  
Artesia, New Mexico 88210  
Office: 575.746.8768  
Fax: 575.746.8905  
Cell: 575.602.3826  
Emergency: 866.742.0742  
Email: [kwilson@talonlpe.com](mailto:kwilson@talonlpe.com)  
Web: [www.talonlpe.com](http://www.talonlpe.com)



Better Business Bureau Torch Award for Marketplace Ethics: 2010 Winner, 2009 Finalist  
Staples Foundation for Learning Hall of Fame Recipient: 2010  
ICIC and Business Week- Top 100: 2010, 2009, 2008, 2007, 2006  
Inc. 500/5000: 2012, 2011, 2010, 2009, 2008, 2007