

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	FNR 26 Federal #1 CTB	Facility Type	Gathering
Surface Owner	BLM	Mineral Owner	
		API No. 30-015-30412 (nearest well)	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	26	23S	30E					Eddy County, NM

Latitude N 32.27025° Longitude W 103.85793°

NATURE OF RELEASE

Type of Release	Fresh water	Volume of Release	25 bbls	Volume Recovered	0 bbls
Source of Release	While trying to flush salt from a flow line, water was released	Date and Hour of Occurrence	01/21/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD; Jennifer Van Curen- BLM		
By Whom?	Kathy Purvis	Date and Hour	01/23/14		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

NM OIL CONSERVATION

ARTESIA DISTRICT

JUL 22 2014

Describe Cause of Problem and Remedial Action Taken.*

RECEIVED



While trying to flush out salt from a flow line, 25 bbls of fresh water leaked onto the ground. No fluids were recovered.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 25' x 25' with part of the leak on location and part of the leak off location. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD on 03/04/2014 and approved by Jennifer Van Curen of the BLM via email on 03/09/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:			
Printed Name:	Chancey Summers	Approved by Environmental Specialist:	
Title:	HES Specialist	Approval Date:	7/28/14
E-mail Address:	Chancey.Summers@oxy.com	Expiration Date:	NA
Date:	7-10-14	Conditions of Approval:	Final
Phone:	(575) 397-8216	Attached	<input type="checkbox"/>

* Attach Additional Sheets If Necessary