

1623 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1227 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBES OGD

Form C-141  
Revised August 8, 2011

SEP 2 4 2014  
Site ID 15 Only if appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: ConocoPhillips	Contact: Jose A Zepeda
Address: 1410 N West County Road	Telephone No: 575-391-3165
Facility Name: Britt B Battery	Facility Type: Battery

Surface Owner: Federal Lease	Mineral Owner: N/A	API No. Fed Lse #LC031621B
------------------------------	--------------------	----------------------------

LOCATION OF RELEASE

30-025-0611 71

Unit Letter E	Section 15	Township 20S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County LEA
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release: OIL	Volume of Release: 25 8 pp	Volume Recovered: 1.0
Source of Release: PRV on Production Separator	Date and Hour of Occurrence 01/06/14 0630 am	Date and Hour of Discovery SAME
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Jose A Zepeda	Date and Hour: 01/07/2014 0655	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*

Describe Area Affected and Cleanup Action Taken.\*

On 01/06/14 @ ~0630 @ the Britt B Battery, there was an accidental discharge of ~8 bbls of oil from PRV on production separator. COPC MSO received a high level alarm for the separator. Upon arrival COPC MSO discovered a PRV on production separator that had popped off and spilled oil. Due to the freezing temperature the line froze and the PRV on the production separator popped off and spilled oil to ground. The line was shut in and vacuum truck was contacted. Vacuum Truck picked up 5 bbls of oil. The spill site will be remediated in place in accordance with COPC and NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: JOSE A ZEPEDA

Printed Name: Jose A Zepeda

Title: LEAD HSE

E-mail Address: Jose. A. Zepeda@conocophillips.com

Date: 01/06/2014

Phone: 575-391-3158

Approved by Environmental Specialist:

Approval Date: 9-24-14

Expiration Date: 11-24-19

Conditions of Approval:

Site sample reports  
Releases & releases area report  
NMOCD guidelines. Submit  
Final C-141 by 11-24-14.

Attached ☐

IRP-3009

\* Attach Additional Sheets If Necessary

ogrid 217817

N70 1426 741065

P70 1426 741513

SEP 23 2014