

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

CONSERVATION  
ARTESIA DISTRICT

SEP 22 2014

Form C-141  
Revised August 8, 2011

RECEIVED  
Submit to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU-409H Spill location is 2848 ft. S.W. of the PLU-409H (2RP-2135)	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-41136
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter B	Section 28	Township 24S	Range 31E	Feet from the 263	North/South Line North	Feet from the 2123	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude N 32.194714 Longitude W 103.780923

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 180 bbbbls	Volume Recovered: 100 bbls
Source of Release: Flange failure on the water transfer pump	Date and Hour of Occurrence: 12/25/13 Time approximately	Date and Hour of Discovery: 12/25/13 at 8:30 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency #104 and BLM	
By Whom? Tony Savoie	Date and Hour: 12/25/13 at 9:20 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* While fracing the PLU-409H an 8" flange broke on the discharge side of the water transfer pump. The pump was shut down and the valve on the discharge of the pump was closed. Vacuum trucks were standing by during the water transfer and were immediately dispatched to the spill location. The lines were switched on the pump and the water transfer continued.

Describe Area Affected and Cleanup Action Taken.\* The spill impacted approximately 40,600 sq.ft. of the Buck Jackson caliche road and approximately 8,600 sq.ft. of pasture area at the point of release and where the water ran off the road way and into the pasture.

**DFSI was retained to perform the remediation for BOPCO. The remediation started on 12/30/13 and ended on 2/16/14 during this time frame approximately 3,254 cubic yards or roughly 3,706 tons of contaminated soil was hauled to Lea Land. Please reference the Site Closure Report 6/17/14.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: 	
Title: Waste Management and Remediation Specialist	Approval Date: 9/24/14	Expiration Date: NA
E-mail Address: tasavoie@basspet.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 9/19/14	Phone: 432-556-8730	

\* Attach Additional Sheets If Necessary