HOBSOCD

District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division

Form C-141

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

1220 South St. Francis Dr. Santa Fe, NM 87505 Release Notification and Corrective Action

						OPERATOR Initial Report Fina						Report	
Name of Co		Oxy Permia				Contact (							
		tanolind Rd,				Telephone No. (575) 397-8216							
Facility Name Covington A Federal #9 CTB						Facility Type Battery location							
Surface Owner BLM Mineral Owner						API No. 30-025-32036							
LOCATION OF RELEASE													
Unit Letter	Section	Township	Range	Feet from the		/South Line	Feet from the	East/West Line	County	County			
N	25	22S	32E		,				Lea County, NM			ļ	
Latitude N 32.35681° Longitude W 103.63049°													
NATURE OF RELEASE													
Type of Release Oil						Volume of Release 15 bbls Volume Recovered 0 bbls							
Source of Release Dump valve on equalizing line was closed and caused the water to go to the oil tank						Date and Hour of Occurrence Date and Hour 09/30/2014				ur of Discovery			
Was Immediate Notice Given?						If YES, To Whom?							
✓ Yes ☐ No ☐ Not Required							Tomas Oberding-NMOCD; Sol Hughes- BLM						
By Whom? Kathy Purvis						Date and Hour 10/01/2014 @ 4:40 pm							
Was a Watercourse Reached?  ☐ Yes ☑ No						If YES, Volume Impacting the Watercourse.							
If a Watercourse was Impacted, Describe Fully.*													
Describe Corner of Problem and Described Assistant Tales #													
Describe Cause of Problem and Remedial Action Taken.*													
A dump valve to an equalizing line was closed causing the water to go to the oil tank and spill 15 bbls of oil onto the ground. No fluid were recovered and													
the dump valve was opened correctly.													
Describe Area Affected and Cleanup Action Taken.*													
The affected	area is appr	oximately 6';	x 25' and i	is on location. Re	emediat	ion will be co	mpleted in accord	ance with a remed	ation plan	approv	ed by		
NMOCD and		- 7							F	11	,		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
regulations al	1 operators	are required to	o report an	ıd/or file certain r	elease r	otifications a	nd perform correc	tive actions for rel	eases which	ı may e	endanger	r	
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
federal, state, or local laws and/or regulations.													
						OIL CONSERVATION DIVISION							
Signature:						- They							
Printed Name: Chancey Summers						Approved by Environmental Specialist:							
Title: HES Advisor A					Approval Da	e: 18 70 -14	Expiration	Expiration Date: 12-10-14					
E-mail Addre	ss: Chan	cey.Summers	@oxy.con	<u>]</u>		Conditions of	Approval:		Attache	d 🏻			
Date: (0-(0-19) Phone: (575) 397-8216						Petrute & rangente over on pa Nomoco graites. Subat frank C-141 by 12-10-19			1RP-3376				
Attach Addit				(5) 57, 62,	<del>_</del>	NMOCDE	mites. Su	and break	0	grid	1669	16	
						C-14169 12-10-19 14				19 28 728909			
						,					7291		