

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

Form C-141
Revised August 8, 2011

OCT 14 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Resolute Natural Resources Co., LLC	Contact	Mike McKee, EH&S Coordinator
Address	1675 Broadway, Suite 1950 Denver, CO 80202	Telephone No.	303 573 4886 x 1625
Facility Name	TD Pope 36-1 Well	Facility Type	Production Well
Surface Owner	State of NM/Leased by Dickie Wheeler	Mineral Owner	
		API No.	30-025-05209

LOCATION OF RELEASE

Unit Letter M	Section 36	Township 14S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude 33.05444 Longitude 103.160758

NATURE OF RELEASE

Type of Release	~9 bbl oil and 20 bbl produced water	Volume of Release	~29 bbl	Volume Recovered	None - Misted on to Surface Soil
Source of Release	A cow opened a bleeder valve on the wellhead	Date and Hour of Occurrence	4/26/14 ~8:00 am	Date and Hour of Discovery	4/26/14 8:30 am
Was Immediate Notice Given? (Not within 24 hours)	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mr. Geoffrey Leking - District I		
Verbal Notice on 4/28/14					
By Whom?	Mike McKee	Date and Hour	4/28/14 2:45 pm mountain time		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Resolute personnel discovered that a cow opened a bleeder valve on the wellhead spraying production fluid adjacent to the wellhead. The handle on the valve will be removed to prevent future occurrences.

Describe Area Affected and Cleanup Action Taken.*

The sprayed fluid volume affected the area immediately adjacent to the wellhead. Cleanup of this affected area will include utilizing a backhoe to scrape surficial soils impacted by the spray and temporarily stockpiling. The surface area exposed by the scraping will be sampled, with collected samples submitted for laboratory analysis of benzene, toluene, ethylbenzene, and total xylenes (BTEX), total petroleum hydrocarbons (TPH), and chlorides. Following confirmation that affected surficial soils have been adequately removed, clean material will be brought in and the stockpile of impacted soil will be transported to Gandy-Marley for treatment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Mike McKee	Approved by Environmental Specialist:		
Title: Environmental, Health & Safety Coordinator	Approval Date: 10-14-14	Expiration Date: 12-19-14	
E-mail Address: mmckee@resoluteenergy.com	Conditions of Approval: Site Supervisor Required. Resolute & Resolute area upon		Attached <input type="checkbox"/>
Date: 4/30/14 Phone: 303 573 4886 x 1625	NMOCD gander. Submit Final C-141 by 12-14-14		19P-3377

* Attach Additional Sheets If Necessary

NMOCD gander. Submit Final C-141 by 12-14-14

Ogid 295770
N 701428 735124
P 701428 737893

OCT 17 2014